

6000 CNC CONTROL HELP MENU'S



The **HELP MENU'S** are access by pressing.



This can be done from either Manual or Edit.



Manual mold soft keys



Edit mold soft keys




First **Help** screen













Note: The center of the screen. There are two different displays, one has text about **Help** the other shows the program as it is being entered.




will toggle these screens.



There are two different set of soft keys , as shown above.

F1		Arrow up and around to desired selection.
F2		Arrow down and around to desired selection.
F3		Not used.
F4		Text changes center of screen to display program.
F5		Selects required cycle. Enter will as do this.
F6		ReEdits a cycle after it is already in a program.
F7		Goes back to edit without saving last set of inputs.
F8		Accepts inputs and stays in HELP.
F9		Goes back to previous page in HELP menu.
F10		Exits to EDIT page and saves inputs.


Section as shown below these are the major defaults. Highlight the required in put and


press either **Select** or  enter.

Incr.	G91	i
Absolute	G90	m
		f
		g
MM	G71	F
Inch	G70	G
		P
YZ Plane	G19	r
XZ Plane	G18	t
XY Plane	G17	
Feed	G1	
Rapid	G0	1

Use up arrow key to move high to next selection.


Press the number 2 key or arrow up to number 2 .

Press either **Select** or  enter



Note:- the reverse color around Compensation.

Press either **Select** or  enter



1. Puts a **G40** into program comp off.
2. Enters **G41** into program cutter comp left.
3. Enters **G42** into program cutter comp right.
4. **G68** rotates a shape around a center.
5. **G72** scale program to required size.

Rotation G68

G68 - ROTATION

NOTE: G68 alone, cancels rotation.
If P and L used, S must be used.

Rotation ctr.I

Rotation ctr.J

First Angle S

Angle C +0.00000

Subprogram # P

Num of Times L

Center of rotation X axis.

Center of rotation Y axis.

Start angle when using loop.

Angle between loops or single shot.

Subroutine #.

Number of repeats.

Note:The only entry that has to be program is **C** because it has 0 (Zero's) next to it.

This cycle can be programmed in main program or in a subroutine. If programmed in the main, the cycle is entered and then the dimension of the shape and turned off with a **G68**.

```
G00 G17 G70 G90 T0 Z0
T1
S1000 M3
X5 Y4
G68 I5.0000 J4.0000 C45.00000
G0 X7 Y4 Z.1
G1 Z-.2
X9
Z.1
G68
G0 T0 Z0
X-1 Y-1
M2
```


This example is show rotation just one time not using a subroutine,note the G68 to turn off rotation.

```
G00 G17 G70 G90 T0 Z0
T1
S1000 M3
X5 Y4
G68 I5.0000J4.0000S0.0000C45.0000P1L8
G0 T0 Z0
X-1 Y-1
M2

O1
G0 X7 Y4 Z.1
G1 Z-.2
X9
Z.1
M99
```


Example on left show rotation using subroutine, note there is no **G68** turning off rotation ,it's not required when programming this way.

Scaling G72



When using scaling if there are any the axis must be scaled the same on both of these axis. If part is required to be half size .5 would be factor. G72 alone will turn off scaling.

Lines



Press # 3 either




or



enter.


Screen will now appear as below.

Inputs will change according to which plane is active.



- 2. **X** axis input only.
- 3. **Y** axis input only.
- 4. **X** and **Y** axis.
- 5. **Angle** and **X** axis.
- 6. **Angle** and **Y** axis.
- 7. **Angle** and **Radius**
- 8. **Radius** and **X** axis
- 9. **Radius** and **Y** axis

Arc's



Press # 4 either




or



enter.

Screen will now appear as below.




Tool must be at start point before inputting arc's

Centers of arcs $X=I$, $Y=J$ and $Z=K$

Inputs will change according active plane.

2. **Radius and End Point.**
3. **Center and End Point.** This can be used for helical interpolation (thead mill.)
4. **Center and X End Point.**
5. **Center and Y End Point.**
6. **Center and Angle.** Angle is dependant Absolute or increamental.
7. **Arc and Line.** Inputs are Radius, Angle and End Point X and Y
8. **Line and Arc.** Inputs are Angle, Radius and End Point X and Y
9. **Arc and Arc.** Inputs Center X and Y first arc, Center X and Y second arc and End Point X /Y

Corner Rounding And Chamfering



Press # 5 either




or




enter.

Screen will now appear as below.




- 2. Radius** One shot corner rounding. Inputs mid point X / Y, radius and end point X/Y.
- 3. Chamfer** One shot chamfer. Inputs mid point X/Y, chamfer and end point X/Y.
- 4. Corner Radius** Modal command puts radius on all intersects.
- 5. Corner Chamfer** Modal command puts chamfer on all intersects.
- 6. Cancel** Cancels #4 and #5

Multiple line, arc and chamfer moves.



Press # 6 either **Select** or  enter.


Screen will now appear as below.



**Tool must be positioned at start point.
Inputs will change according to active plane.**

- 2. Definition** Inputs first angle, second angle and end point.
- 3.Radius** Inputs first angle, radius, second angle and end point.
- 4.Chamfer** Inputs first angle, radius, second angle and end point.
- 5.Rad/Rad** Inputs first angle, first radius, second angle, mid point, second radius and end point.
- 6.Chamf/Chamf** Inputs first angle, first radius, second angle,
- 7.Rad/Chamf** Inputs first angle, radius, second angle, mid point X/Y chamfer and end point.
- 8.Chamfer/Rad** Inputs first angle, chamfer, second angle, mid point X/Y, radius and end point.

Pockets



Press # 7 either




or



enter.

Screen will now appear as below.

**Cutter comp is built into all pocket except Mold Rotation.
X and Y centers are Optional but if not entered will assume it is positioned at center of pocket.**



#2. Frame Milling.

#3. Hole Milling.

#4. Circular Pocket.

#5. Rectangular Pocket.

#6. Area Clearance.

#7. Mold Rotation.

#8. Elbow Milling.

#9. Draft Pocket.

+/- . Plunge pockets.

Leave island in middle of pocket.

Enlarges existing hole, used on smaller holes.

Cuts flat bottom circular pocket.

Cuts flat bottom rectangular pocket.

Cuts irregular shape pocket and takes profile cut.

Rotates a profile around an axis.

Produces a radial groove.

Rectangular pocket with angled sides.

Rectangular and circular pocket plunging straight down.

Plunge Pockets

#2. Circular Plunge Pocket


Plunges straight into material.

#3. Rectangular Plunge Pocket.

Plunges straight into material.

Frame pocket G75


Only the input with in Zeros have to be entered the rest are optional. It will assume being at the center of pocket if no dimension are entered.



X Center	X	Center of pocket X axis.If not entered will assume tool is at center of pocket.Optional
Y Center	Y	Center of pocket Y axis.If not entered will assume tool is at center of pocket.Optional
Length	M	Length of island (X).
Width	W	Width of island (Y).
Start Hgt.	H	Start height .1inch or 2mm above top surface of pocket.
Z Depth (abs)	Z	Absolute depth to bottom of pocket.
Stepmover	A	Cut per pass, not to exceed 70% of cutter dia. Negative value path will climb mill.
Max. Z cut	B	Depth per pass Z axis.Optional
Ramp Feed	I	Feedrate when feeding down into pocket. Optional
Rough Feed	J	Feedrate roughing pocket.Optional
Inside Rad.	U	Radius on corners of island.
Outside Rad.	V	Radius on outside, will assume cutter radius if no entry. Optional
Frame Width	C	Dimension from island to outside.
Finish Stock	S	Amount of material left for finish pass.Optional
Finish Feed	K	Feedrate for finish pass.Optional
Retract Hgt.	P	High retract allows tool to be move above the surface part when finished. Optional

Hole Milling G76

A good use for this cycle to produce small counterbores.



Diameter	D	Diameter of pocket.
Rough Feed	J	Feedrate roughing.
Finish Stock	S	Finish Stock.
Finish Feed	K	Feedrate finish pass.

Circular pocket G77

G77 CIRCULAR POCKET MILLING
 NOTE: Negative diameter = CW.

X Center	X	
Y Center	Y	
Z Start Hgt.	H	+0.0000
Z Depth(abs)	Z	+0.0000
Diameter	D	+0.0000
Stepover	A	
Z Max. cut	B	
Rough Feed.	I	
Finish Stock	S	
Finish Feed.	K	
Retract Hgt.	P	

X Center	X	Center X axis.	Optional
Y Center	Y	Center Y axis.	Optional
Z Start Hgt.	H	Start height .1 above surface to be cut into.	
Z Depth (abs)	Z	Absolute Z depth.	
Diameter	D	Diameter of pocket, comp built in.	
Stepover	A	Move over per pass.	Optional
Z Max. cut	B	Max. Z depth per pass.	Optional
Rough Feed.	I	Feedrate roughing.	Optional
Finish Stock	S	Amount of material left for finish pass.	Optional
Finish Feed.	K	Finish pass feedrate.	Optional
Retract Hgt.	P	High return when finished.	Optional


Rectangular Pocket. G78

G78 RECTANGULAR POCKET MILLING
 Neg. stepover = CW.

X Center	X	
Y Center	Y	
Length	M	+0.0000
Width	W	+0.0000
Z Start Hgt.	H	+0.0000
Z Depth(abs)	Z	+0.0000
Corner Rad.	U	
Stepover	A	
Z Max. Cut	B	
Ramp Feed.	I	
Rough Feed.	J	
Finish Stock	S	
Finish Feed.	K	
Retract Hgt.	P	


X Center	X	Center of pocket X	
Y Center	Y	Center of pocket Y	
Length	M	Actual length X axis	
Width	W	Actual width Y axis	
Z Start Hgt.	H	.1 above surface to be cut	
Z Depth (abs)	Z	Absolute depth of pocket	
Corner Rad.	U	Radius in corners	
Stepover	A	70% of cutter or less	
Z Max. Cut	B	Max depth per pass	
Ramp Feed	I	Feedrate on 3 axis first move	
Rough Feed	J	Feedrate for roughing	
Finish Stock	S	Amount of stock for finish cut	
Finish Feed	K	Finish feedrate	
Retract Hgt.	P	Retract after finished.	

Area Clearance G169.




Input Sub #	W	Subroutine number.
X	X	X position tool will Z down into part
Y	Y	Y position tool will Z down into part
Z Start Hgt.	H	Start height .1 above top of pocket
Z Depth (abs)	Z	Total depth of pocket absolute
Cut Angle	C	Used if starting in middle of radius
X Start	D	Position of cut at start X axis. Optional
Y Start	E	Position of cut at start Y axis. Optional
Stepover	A	Cutter stepover each pass
Z Max. Cut	B	Max depth of cut per pass.
Ramp Feed	I	Ramp feedrate Z down
Rough Feed	J	Rough feedrate
Finish Stock	S	Stock left for finish pass
Finish Feed	K	Finish feedrate
Retract Hgt.	P	Retract after finished.

Mold Rotation G45




Start Angle	A	Angle where rotation is going to start
End Angle	B	Angle where rotation is going to end
Num of Cycles	C	1 cycle equals 1 Fwd and 1 Rev. Sub.
Num of Fwd Sub	F	Sub. Profile forward direction
Num of Rev Sub	R	Sub. Profile Reverse direction
Axis of Rotation	X	Axis rotation is around X,Y or Z
Other axis CL	I	Center line X or Y if not Zero
Centerline	J	Center line Z Axis if not Zero
Rotation Angle	K	Angle rotation Z axis only

Elbow Milling G49




Start Radius	B	Radius at start of Elbow
End Radius	K	Radius at end of Elbow
Included Angle	A	Included angle
Num of Cycles	C	Sub. Profile forward direction
X Center	I	Sub. Profile Reverse direction
Y Center	J	Axis rotation is around X,Y or Z
Direction CCW+	D	Center line X or Y if not Zero
End Angle	F	Center line Z Axis if not Zero
Start Angle	E	Angle rotation Z axis only
Ctr. Line Radius	R	Radius at center of elbow
Rapid Height	Z	Starting height above surface.
Start Height	H	Z height to start
Rough Feed	U	Rough feedrate
Finish Stock	S	Amount of stock for finish pass
Finish Feed	V	Feedrate for finish cut

Draft Pocket G73




Length, bottom	X	Length at bottom of pocket.	required
Width, bottom	Y	Width at bottom of pocket.	required
Start Height	H	Height above part to rapid.	required
Z Depth (abs)	Z	Absolute depth	required
Lower Left Rad.	A	Lower left Radius	required
Lower Right Rad.	B	Lower right radius	optional
Upper Left Rad.	C	Upper left radius	optional
Upper Right Rad.	D	Upper right radius	optional
Draft Angle	E	Draft angle Degrees	required
Z step Rough	I	Depth per pass in Z axis	required
Max XY Steppover	V	Maximum steppover XY	optional
Finish Stock XY	S	Finish stock XY	optional
Z step Finish	Q	Z step finish pass	optional
Finish Feed	R	Finish feedrate	optional
Flat 0, Ball 1	W	Flat mill = 0 Ball mill = 1	optional


Note: Tool must be positioned at center of radius bottom left corner.
 Center of pocket must be cleared before using this cycle.
 When using flat endmill will go to programmed depth.
 If ball endmill uses will only go to depth minus cutter radius, .5 mill
 Absolute depth -1 actual depth it would go to is -.75.



High lite plunge pockets press




Plunge Circular Pocket G177









X Center	X	X Center X axis	Optional
Y Center	Y	Y Center Y axis. Same as above.	Optional
Z Start Hgt.	H	Start height .1 above surface to be cut.	
Z Depth (abs)	Z	Absolute Z depth.	
Diameter	D	Diameter of pocket, comp built in.	
Stepover	A	Move over per pass.	Optional
Z Max. cut	B	Max. Z depth per pass.	Optional
Z Feedrate	I	Feedrate plunging	Optional
Rough Feed.	J	Feedrate roughing.	Optional
Finish Stock	S	Amount of material left for finish pass.	Optional
Finish Feed.	K	Finish pass feedrate.	Optional
Retract Hgt.	P	High return when finished.	Optional

Plunge Pocket Pocket G178



X Center	X	Center of pocket X
Y Center	Y	Center of pocket Y
Length	M	Actual length X axis
Width	W	Actual width Y axis
Z Start Hgt.	H	.1 above surface to be cut
Z Depth (abs)	Z	Absolute depth of pocket
Corner Rad.	U	Radius in corners
Stepover	A	70% of cutter or less
Z Max. Cut	B	Max depth per pass
Ramp Feed	I	Feedrate on 3 axis first move
Rough Feed	J	Feedrate for roughing
Finish Stock	S	Amount of stock for finish cut
Finish Feed	K	Finish feedrate
Retract Hgt.	P	Retract after finished.




<p>SPIRAL</p>  <p>G06 3</p>		<p>FACING</p>  <p>G170 5</p>	<p>CIRC PROFILE</p>  <p>G171 7</p>	<p>RECT PROFILE</p>  <p>G172 8</p>
<p>ELLIPSE</p>  <p>G05 2</p>	<p>If they are not active, from group 1 Plane, inch/metric, and absolute/incremental can be selected.</p> <p>Move the cursor around the screen with the arrow keys or by number required.</p>			

- #2. Ellipse. Produces an ellipse, uses special cutter comp.
- #3. Spiral. Will cut a tapered thread.
- #5. Facing. Faces large surfaces.
- #7. Circular Profile. Cut circle either inside or outside.
- #8. Rectangular Profile. Cut rectangle inside or outside.

Ellipse G05

Note: All dimensions are INCREMENTAL.




End Horizontal	X	Distance from start to end X axis.
End vertical.	Y	Distance from start to end Y axis.
Center Horizontal	I	Distance to center from start.
Center Vertical	J	Distance to center from start.
Half length	A	Half length of ellipse x axis
Half width	B	Half width of ellipse Y axis.
CCW +,CW -.	L	Direction of cut.

Cutter comp for ellipse uses **M1040** X0 = off, X1 = outside and X2 = inside.
Cutter must be positioned in compensated position before ellipse is programmed.

Spiral G06


Note: All dimensions are INCREMENTAL.



End Horizontal	X	Distance from start to end X axis.
End vertical.	Y	Distance from start to end Y axis.
End Depth Z	Z	Distance from start to end Z axis.
Center Horizontal	I	Distance to center from start.
Center Vertical	J	Distance to center from start.
Number of revolution	L	Number of turn it will make.
CCW +,CW -.		Direction of cut.

No compensation available for spiral.


Facing G170



Length	X	Incremental length X axis.
Width	Y	Incremental width Y axis.
X Stepper	A	Stepper X .
Y Stepper	B	Stepper Y.
Feedrate	F	Feedrate.
Z Start hieght	H	Start height .1 above surface.
Z Depth Absolute	Z	Finish depth.
X Start	D	Start X axis.
Y Start	E	Start Y axis.


Note: Only A or B not both can be used.
Cutter will step away from start corner by half the cutter diameter.

Circular profile G171












- Center X.** X X Center (optional).
- Center Y.** Y Y Center (optional).
- Start height.** H Start height above surface to be cut.
- Diameter.** D Diameter of pocket (actual).
- Z depth (absolute).** Z Depth to be cut (absolute).
- Ø = inside, 1 = outside.** A 0 inside ,1 outside of circle.
- Ramp Distance.** R Size of ramp on radius.
- Z Maximum cut.** B Maximun depth in Z per pass.
- Finish Stock.** S Amount of stock left for finish cut.
- Z Feedrate.** I Feedrate in Z axis.
- Rough feedrate.** J Feedrate for roughing.
- Finish Feedrate.** K Feedrate for finishing.
- Retract height.** P High retract if higher than H value.

Rectangular Profile G172



- Center X.** X X Center (optional).
- Center Y.** Y Y Center (optional).
- Start height.** H Start height above surface to be cut.
- Length** M Length of pocket X axis (actual).
- Width..** W Width of pocket Y axis (actual)
- Z depth (absolute).** Z Depth to be cut (absolute).
- Ø = inside, 1 = outside.** A 0 inside ,1 outside of circle.
- Ramp Distance.** R Size of ramp on radius.
- Corner radius** U Radius in corners.
- Z Maximum cut.** B Maximun depth in Z per pass.
- Finish Stock.** S Amount of stock left for finish cut.
- Z Feedrate.** I Feedrate in Z axis.
- Rough feedrate.** J Feedrate for roughing.
- Finish Feedrate.** K Feedrate for finishing.
- Retract height.** P High retract if higher than H value.


Drilling Cycles G80 Series

 <p>COUNTERBORE G82 3</p>	 <p>PECKING G83 4</p>	 <p>TAPPING G84 5</p>	 <p>BORE/BI G85 6</p>	 <p>BORE/UNI G86 7</p>	 <p>CHIP BREAK G87 8</p>
 <p>DRILLING G81 2</p>	<p>If they are not active, from group 1 Plane, inch/metric, and absolute/incremental can be selected.</p> <p>Move the cursor around the screen with the arrow keys or by number required.</p> <p>Press SELECT key to pick the item. Combinations of items are not allowed in the same block and if selected, an error message will be displayed.</p> <p>Press ACCEPT to insert data into the program and remain in Help, press EXIT to insert data into the program and return to the Editor.</p> <p>All of the G80 series cycles are modal and will activate the Z axis at each X,Y coordinate until canceled with a G80 code.</p> <p>NOTE: Must program drill cycle before bolt circle.</p>				 <p>FLAT BORE G89 9</p>
<p>Incr. G91 Absolute G90</p> <p>MM G71 Inch G70</p> <p>YZ Plane G19 XZ Plane G18 XY Plane G17</p> <p>CANCEL G80 1</p>					 <p>BOLT CIRCLE G79 $\frac{+}{-}$</p>
<p>PATTERN G179 .</p>					
<p>↑ ↓ Text Select Abort Accept Prev Exit</p>					

Note:That there is now a **G80** in the first box on left.


All **G80** cycles must be turn OFF with a **G80** as soon as drill operation is finished.

Basic Drilling Cycles G81




- Finish Depth.** Z Finish depth of hole.
- Start Hgt.** R Start height above surface to be drilled.
- Feedrate.** F Feedrate for drilling.
- Return Hgt.** P Return height if higher than R plane.

Counter Boring Cycles G82




- Finish Depth.** Z Finish depth of hole.
- Start Hgt.** R Start height above surface to be drilled.
- Feedrate.** F Feedrate for drilling.
- Dwell time** D Dwell time qat bottom of hole.
- Return Hgt.** P Return height if higher than R plane.

Peck Drilling Cycles G83




- Finish Depth.** Z Finish depth of hole.
- Start Hgt.** R Start height .1 above surface to be drilled.
- Feedrate.** F Feedrate for drilling.
- Maximun Peck** I Maximun peck before retracting.
- Return Hgt.** P Return height if higher than R plane.

Tapping Cycles G84




- Finish Depth.** Z Finish depth of hole.
- Start Hgt.** R Start height above surface to be drilled.
- TPI/Lead.** F TPI if inch/Lead if MM.
- Spindle.** S Spindle sync. 0 = OFF, 1 = ON
- Return Hgt.** P Return height if higher than R plane.
- Dwell time** D Dwell at bottom if necessary.

Boring Cycles G85




- Finish Depth.** Z Finish depth of hole.
- Start Hgt.** R Start height above surface to be drilled.
- Feedrate.** F Feedrate for drilling.
- Return Hgt.** P Return height if higher than R plane.

Boring Cycles One Direction G86




- Finish Depth.** Z Finish depth of hole.
- Start Hgt.** R Start height above surface to be drilled.
- Feedrate.** F Feedrate for drilling.
- X Backoff.** I Backoff before retracting from hole.
- Dwell time.** D Dwell to flat bottom hole.
- Return Hgt.** P Return height if higher than R plane.
- Index Angle.** C Index angle to orient spindle to backoff.

Chip Breaking Cycle G87




- Finish Depth.** Z Finish depth of hole.
- Start Hgt.** R Start height .1 above surface to be drilled.
- Feedrate.** F Feedrate for drilling.
- First Peck.** I Amount of first peck.
- Delta Peck.** J Amount to decrease peck each peck.
- Minimum Peck.** K Smallest peck amount.
- Chp. Brk. Inc.** W Retract for chip break
- Retract Depth.** U Depth full retract accrues.
- Return Hgt.** P Return height if higher than R plane.

Flat Bottom Boring Cycle G89



- Finish Depth.** Z Finish depth of hole.
- Start Hgt.** R Start height above surface to be drilled.
- Feedrate.** F Feedrate for drilling.
- Dwell.** D Dwell in second at bottom of hole.
- Return Hgt.** P Return height if higher than R plane.

Bolt Hole Circle Drilling G79



- Center.** X Center X axis.
- Center.** Y Center Y axis.
- Index Angle.** C Angle to rotate 0 angle from 3 o'clock.
- First Angle.** A Angle of first hole from 0.
- Last Angle.** B Angle of last hole, if full pattern not required.
- Number Holes.** H Number of holes to drill.
- Diameter.** D Diameter of pattern.
- Radial Path.** R If 1 is entered will move radially around pattern

Hole Pattern Dilling G179



- X Start.** X Start point X axis.
- Y Start.** Y Start point Y axis.
- Angle.** C Angle If pattern is rotated.
- X Length.** A Distance from first to last hole X axis.
- Y Width** B Distance from first to last hole Y axis.
- Num. Holes X.** D Number of holes X axis.
- Num. Holes Y.** E Number of holes Y axis.
- X Increment.** U Distance between holes X axis.
- Y Increment.** V Distance between holes Y axis.
- Pat.=0 Sqr.=1** W Pattern as shown or square around outside.

Use D & E or U & W not both.

G-Code without Graphics

MISCELLANEOUS G CODES	
G04 Dwell.	←
G09 Exact Stop (Single Block).	←
G22 Stroke Limit.	←
G28 Reference Point Return.	←
G29 Return from Reference Point.	←
G53 Fixture Offset(s) (Coord. Syst. Select)	←
G61 Exact Stop Mode (Contouring Mode OFF).	←
G64 Contouring Mode (Exact Stop Mode OFF).	←
G65 Macro Call, Single (Non-Modal)	←
G66 Macro Call, Modal.	←
G67 Cancel Modal Macro	←
G92 Preset Zero.	←
G94 Per Minute Feed	←
G95 Per Revolution Feed.	←

Dwell In seconds with Tn
Exact stop will stop exactly in position one shot.
Stroke Limit set a box that tool cannot move outside or inside.
Reference Point Return sends machine home in designated axis.
Reference Point Return
Fixture offset Absolute zero shift from Home.
Exact Stop will stop after each move to get into exact position.
Contouring Mold continuous path no stops between moves.
Macro Call one shot user written macro.
Macro Call modal macro has to be turned off.
Cancel Macro cancel modal macro.
Preset Zero incremental zero shift canceled by G53 or homing.
Feed Per Minute feed in inches per minute.
Feed Per Revolution feed in inches per revolution.

Miscellaneous M-Codes

M-CODES	
M0 Program Stop.	←
M2 End of Program	←
M3 Spindle ON FWD.	←
M4 Spindle ON REV.	←
M5 Spindle OFF.	←
M8 Coolant ON.	←
M9 Coolant OFF.	←
M30 Jump to New Program.	←
M98 Call Subprogram.	←
M99 End Subprogram.	←
M100 Mirror Image.	←
M105 Dry-Run, All Axes.	←
M106 Dry-Run, NO Z Axis.	←
M107 Dry-Run OFF (Cancel M105, M106)	←

Program Stop stop program until START is pressed to to continue.
End of Program end of main program.
Spindle ON Forward turn spindle ON FORWARD.
Spindle ON Reverse turns spindle ON REVERSE.
Spindle OFF turns spindle OFF.
Coolant ON tuns coolant ON.
Coolant OFF turns coolant OFF.
Jump to New Program entered using Pxxxx.
Call Subroutine call a subroutine using Pxx.
End Subroutine Last line of subroutine.
Mirror Image axis need to be entered X,Y or Z.M100 turns OFF
Dry Run All Axis display shows motion but no table movement.
Dry Run NO Z Axis X and Y move no Z axis movement.
Dry Run OFF turns OFF dry run.