

6000 CNC CONTROL Simple Program




CREATING A PROGRAM

From Manual page press



The softkeys will be changed as shown below.



Press



Type the program name (Maximum 8 letters/numbers).

Press Enter to go into program directory



LAWRENCE.G	NICE2.G	SHUTTLE.G	TNC.G
LETR230.G	07_SAMPL.G	SLOTMAC.G	WINDOW-M.G
LETRCAL1.G	PAGODA2.G	SNOWMAN.1	WOMAN.G
LETSAMBL.G	PHIL.G	SNOWMAN.CAM	WY.G
LTRS230.G	POCK.G	SNOWMAN.G	
MAINTTEST.G	POCK.M	SNOWMAN.GEO	
MATT1000.G	POCKETS.G	SNOWMAN.T1	
MER-FIN.G	POCKETS.M	SNOWMAN.T2	
MER-ROU.G	POCKETS1.G	SPIRAL.G	
MERC-ARC.G	POCKETS1.M	SPIRAL.S	
MERC-LIN.G	<u>PROGRAM.G</u>	STOCKVAR.G	
MERC-LIN.M	REPEAT.M	T.G	
MERC1.G	RICH.G	T.NC	
MERC2.G	RON.G	TAPE.G	
MERC3.EXE	ROUGH.G	TAPE.S	
MERC3.G	ROUGH1.G	TAPE3200.G	
MILL.G	ROUGH22.G	TAPE3200.M	
MILL.M	SAM.G	TAPE3200.NCC	
MILL1.G	SAM1.G	TAPPING.G	
MODERN.G	SAM2.G	TC.G	
MONARCH.G	SCHWADA1.G	TEST.G	
NATHAN.G	SCHWEDA.G	TEST2.G	
NATHAN.M	SCHWEDA4.G	THREAD.G	
NICE.G	SHOW98HA.G	TIM.G	

C:\USER SELECTED PROGRAM:


Create	Delete	CAM	List	Select	Draw	Edit	Utility	Exit
--------	--------	-----	------	--------	------	------	---------	------

High light will be on program just created.

Press



This is how screen will appear when entering **EDIT**




Program name




Note: Insert is turn ON ,if not will not go past bottom of page.

Note: Softkeys have change .



This part needs to have 4 hole drilled $.25$ dia and $.5$ deep

Press



High light will be on **G0** press enter



Move high light **G17** , **G70** and **G90** press enter on each of these.

Press **M5** press



Press



it will go into program as shown below.



Top line of program.

```
G00 G17 G70 G90 M5      *RAPID,XY PLANE,INCH,ABSOLUTE,POSITION,SPINDLE OFF
G00 G17 G70 G90 M5      *RAPID,XY PLANE,INCH,ABSOLUTE,POSITION,SPINDLE OFF
T1 M6                   *LOAD TOOL,M6 ONLY REQUIRED IF TOOL CHANGER INSTALLED
S2000 M3                *SET SPINDLE SPEEDAND TURN ON SPINDLE

```

Program: PROGRAM.G (edited) 4:1

Help Del Ins DelBlk PgUp PgDn Move Editing Misc Exit

Program has been edited

Cursor position line and column

Lines 2 and 3 are typed in manually.

The * allows commence into program control will read ignore after it.

Press

F1

HELP

press #9 for **DRILL** press




Screen will appear as shown below.

COUNTERBORE G82 3	PECKING G83 4	TAPPING G84 5	BORE/BI G85 6	BORE/UNI G86 7	CHIP BREAK G87 8
DRILLING G81 2 Incr. G91 Absolute G90 MM G71 Inch G70 YZ Plane G19 XZ Plane G18 XY Plane G17 CANCEL G80 1	*RAPID, XY PLANE, INCH, ABSOLU *LOAD TOOL, M6 ONLY REQUIRED *SET SPINDLE SPEED AND TURN				FLAT BORE G89 9
					BOLT CIRCLE G79 +/-
					PATTERN G179 .

↑ ↓ Text Select Abort Accept Prev Exit

Press #2 for basic drilling, press enter.





Enter values Finish Depth -.5 press down arrow, enter Start Hgt. .1 down arrow and Feedrate 12

Press **F10** **Exit** exits help menu and enters line into program.

```
G00 G17 G70 G90 M5      *RAPID,XY PLANE, INCH,ABSOLUTE,POSITION,SPINDLE OFF
G00 G17 G70 G90 M5      *RAPID,XY PLANE, INCH,ABSOLUTE,POSITION,SPINDLE OFF
T1 M6                   *LOAD TOOL,M6 ONLY REQUIRED IF TOOL CHANGER INSTALLED
S2000 M3                *SET SPINDLE SPEEDAND TURN ON SPINDLE
G81 Z-0.5000 R0.1000 F12.0 *BASIC DRILLING CYCLE
```

The next enter hole positions.

Type **G0 X.75 Y.5**  **X2.75**  **Y1.5**  **X.75** 

Type **G80** 


Cancel drill, this must always in program after last hole.

```
G00 G17 G70 G90 M5      *RAPID,XY PLANE, INCH,ABSOLUTE,POSITION,SPINDLE OFF
G00 G17 G70 G90 M5      *RAPID,XY PLANE, INCH,ABSOLUTE,POSITION,SPINDLE OFF
T1 M6                   *LOAD TOOL,M6 ONLY REQUIRED IF TOOL CHANGER INSTALLED
S2000 M3                *SET SPINDLE SPEEDAND TURN ON SPINDLE
G81 Z-0.5000 R0.1000 F12.0
X.75 Y.5                *FIRST HOLE LOCATION
X2.5                    *NEXT LOCATION
Y2                      *NEXT LOCATION
X.75                    *NEXT LOCATION
G80                     *CANCEL DRILL
Z5                      *RAISE Z AXIS TO ACLEARANCE POSITION
X-2 Y4                  *MOVE X AND Y TO ALLOW ACCESS TO PART
M2                      *END OF PROGRAM_
```

Type in last three lines.




Soft key will change as shown below.



Press **F5** **DISPLAY** cursor will be on **FIT** press enter



This will fits drawing to screen.



Red lines are **RAPID** moves , blue circle are the holes and purple circle is the tool.

Press **F10** **Exit** this brings control back to program page

Press **F6** **Select** to select program ,check that high light is on correct program.

Press **F10** **Exit** go to **Manual**

SETTING PART ZERO.

If using an edge finder , touch edge of part using jog keys.

Go to tool page press **F9** **Tool** press **F1** **OFFSETS**

G53 Offset					
	X	Y	Z	U	W
1.	-10.0000	-10.0000	0.0000	0.0000	0.0000
2.	-20.0000	-10.0000	0.0000	0.0000	0.0000
3.	0.0000	0.0000	0.0000	0.0000	0.0000
4.	0.0000	0.0000	0.0000	0.0000	0.0000
5.	0.0000	0.0000	0.0000	0.0000	0.0000
6.	0.0000	0.0000	0.0000	0.0000	0.0000
7.	0.0000	0.0000	0.0000	0.0000	0.0000
8.	0.0000	0.0000	0.0000	0.0000	0.0000
9.	0.0000	0.0000	0.0000	0.0000	0.0000
10.	0.0000	0.0000	0.0000	0.0000	0.0000
11.	0.0000	0.0000	0.0000	0.0000	0.0000
12.	0.0000	0.0000	0.0000	0.0000	0.0000
13.	0.0000	0.0000	0.0000	0.0000	0.0000

CalibX CalibY CalibZ CalibU CalibW Exit

Cursor to required **OFFSET** using arrow up and down keys.
Move X axis until part is located with edge finder.

Press **F4** **CalibX** is will enter value into table.

Because the edge find is .2 dia the position will be incorrect , press the letter **A** key ,a box as shown below will appear.
Type in **X.1** this will adjust offset to correct position press **ENTER**.

▶Enter axis and adjustment value: X.1_

Repeat for **Y** axis

All offset are taken from machine Home position.

SETTING TOOL LENGTH OFFSETS

Put tool in spindle , bring tool tool down to top of part.

Press **F9** **Tool** high light correct tool number in tool page


press **F8** **CalibZ**

If there are more move Z axis up change to next tool and calibrate it as before,tool #0 must always be active when setting offsets.

Press **F10** **Exit** when all tools are calibrated.

RUNNING PART.

Press **F6** **Auto** turn down feedrate override knob to 10%



Press 

If machine has a tool changer ,it will put tool #1in spindle if not already there.

If no tool changer install it will stop and allow you to change tool if necessary .

When program complete **Z** axis will go up to 5” above part.