

# ACER

**Turning Center**

**Model: JG100/150/200**

**TAIWAN: FORMOSA SPRINGWOOD INTERNATIONAL, INC.**

**NO. 101, 506 LANE SENG-TSO ROAD, SENG KARNG SHARNG,**

**TAICHUNG COUNTY, TAIWAN**

**TEL: 886-4-520-4120**

**FAX: 886-4-2520-4123**

**[WWW.ACERONLINE.NET](http://WWW.ACERONLINE.NET)**

**NJ: KLIM INDUSTRIAL, INC.**

**244N. RANDOLPHVILLE ROAD**

**PISCATAWAY, NJ 08854 USA**

**TEL: (732)752-9100      FAX: (732)752-9101**

**[WWW.ACERONLINE.NET](http://WWW.ACERONLINE.NET)**

**CA: SPRINGWOOD INDUSTRIAL, INC.**

**1062N.KRAEMERPLACE**

**ANAHEIM, CA 92806 USA**

**TEL: (714) 632-9701      FAX: (714) 632-9701**

**[WWW.ACERONLINE.NET](http://WWW.ACERONLINE.NET)**

**2010.10.20**

# **PREFACE**

**Sincerely thank you for using CNC Lathe.**

**Please be completely note and understand about the installation of machine, all the structures and maintenance stated in the operating manual before using the machine.**

**Further, the proper program for processing by CNC Lathe is required. The proper arrangement for processing work piece in standardization should be considered completely before operating.**

# GENERAL SECURITY MEASURES

## General security Measures

1. Please read completely the operating manual before running the machine, especially in the related security and maintenance. To operate the machine should accord with the manual after studying.
2. In addition to turn off the operation door and the protective cover, do not approach the U-turn part and movable part when it is running.
3. Forbidden to start the machine when the protective cover, mutual-lock device and other security devices are dismounted.
4. The work piece and machining tools should be fixed exactly; besides, the tools after being used should not be placed on the movable part.
5. For safety operation, please put on the special clothes (such as working clothes, shoes, hat, goggles).
6. To maintain the machine should be done by professionals listed in the operating manual.

Please follow out the security-measures indicated in the manual and the warning slogans pasted up, and do regard safety-operation as “user’ s duty” to perform. In case that neglecting any kind of warnings will bring damage to anyone as well as to break down the machines.

Please do not tear down and dirty this slogan.

# WARNING

## △Warning

1. For detailed restrictions concerning chuck function, please refer to Appendix "Description of Chuck Operation."
2. When operation spindle revolve, use max. Rpm allowed for spindle accompanied by low speed of max. Rpm allowed for chuck.
3. Make sure to fasten chuck body and chuck claws.
4. Oil cylinder thrust used for chuck Close/Open should be set under limit (See Description of Chuck Operation for reference.)
5. Working parts should be fastened on chuck. Pay particular attention to unbalanced revolve.
6. When using tail stock core spindle for bar support, pay attention to center hole, shape or center thrust. In supporting heavy-duty parts, any breakage in the center hole front end may result in the danger of flying part.
7. During spindle revolving, avoid activating Open/Close switch (Pad Switch) of chuck claw and tail stock core spindle.
8. For pressure setting of chuck oil cylinder, please refer to setting items specified in "Chuck Clamping Force." Centrifugal force generated by claw overhang under high speed rev. will cause sharp reduction of clamp force.
9. Do not remove or modify stroke switch, various interlock of safety guard device.
10. To avoid error movement caused by major noise interference generated by electric arc welding machine and hoister, additional lining should be connected from converter.
11. Cutting tool should be installed within length range. Interference will result from contacting of tool, safety cover and tail stock core spindle if tool exceeds specified length. Read carefully the Tool Manual and abide strictly by the restrictions.
12. Do not use your hand to grasp working parts.
13. Avoid clamping between processing object and core spindle when tail stock core spindle engages in back and forth movement.
14. All installation of electric device should be entrusted to the hands of a responsible person or safety agent. Close contact should be established between the responsible person and safety agent.
15. All parts used in electric machine should be replaced by those specified by the manufacturer. Under no condition shall overload fuse or bronze wire be allowed to use for the machine.
16. Use only those parts that are under quality guarantee.

17. To avoid any failure and error movement of the machine, be careful not to cause any short circuit in NC device, operation panel or high intensity electric board.
18. The accurate parameter specified in the Parameter List should be adopted for machine test run.
19. Operator shall not change or modify any parameter, size or default setting of electric devices. Please contact our service personnel whenever necessary.
20. Do not press keys randomly. In actual operation, press key with accurate movement.
21. When press "Ready" key on the operation panel, first confirm whether indicator is ON upon completion of Ready function.
22. Confirm that the F value of pressure gauge (hydraulic and air pressure) is correct.
23. When conduct initial run of the machine or when the machine is under Stop condition for long period of time (several days), please apply adequate lubricant on the moving surface of the machine.
24. After Power ON, the machine is ready for operation, use manual mode to reset Home.
25. It is necessary for the spindle and feed spindle to warm run before actual operation starts. First auto run the machine for 20~30 minutes with the max rev. or 1/3 of the feed speed. This warm run program contains lots of various functions. It is worthwhile to first try coordinating them (Refer to test run program.)
26. Make sure chuck pressure is strong enough to make claws execute correctly. Whenever chuck Open/Close in an abnormally slow speed, conform the chuck again. When incomplete clamping occurs, please pay special attention to the clamping position of the ring slot and the shape formed by clamping claws.
27. After tool installation, make sure first if there is any interference caused by tool and chuck. Check program with a low feed speed or use empty car function to test run the machine.
28. Abnormal heat may usually be caused by increased resistance from breakage of tool and drill which in turn result in accidental fire. Please prepare fire extinguisher next to the machine when oil cutting agent is being used.
29. Displacement of turret and work table may be caused by blackout or emergency stop of the machine. After power resume, please activate Offset function by using reference point reset function to restart the machine.
30. When conducting cleaning of the machine or other device, please full stop the machine.
31. When leaving the machine upon finishing daily job, first press Ready key on the panel, then press main power OFF of the intensity electric board. Finally, press cut of the power supply switch in the working site to end your work.

# ATTENTION

## Attention

1. Do not remove, smear or destroy posters that contain safety instructions. In case of any vagueness of the writing or missing of posters, don't hesitate to place order with us for new replacement.
2. Make sure the pressure hydraulic oil, lubricant and cutting oil have been adequately filled. In case of any insufficiency, refill in according with specified amount stated in Lubrication List.
3. For normal and safe operation after regular maintenance, please consult and maintain close cooperation with your maintenance technician.
4. It is important that you should record the contents and results of each maintenance and inspection for future reference.

# CONTENTS

## Preface

1	Brief outline	
1-1	Specification	1-1~2
1-2	Appearance and dimension	1-3/1-5
1-3	Layout	1-4/1-6
2	Installation of machine	
2-1	Installation	2-1~3
2-2	Hanging installation	2-4
2-3	Power supply	2-5
3	Lubrication	
3-1	Lubrication for every part and oil supply	3-1~5
4	Structure and maintenance	
4-1	Spindle	4-1~2
4-1-1	Structure and size of spindle	4-3~4
4-1-2	RPM of spindle/thrust curve	4-5~7
4-1-3	Center of spindle adjustment	4-8
4-1-4	Confirmation of turret and central height of spindle	4-9~10
4-2	Tailstock	
4-2-1	Structure and size of tailstock shaft	4-11~12
4-2-2	Thrust of tailstock shaft	4-13
4-2-3	Center of tailstock adjustment	4-14~16
4-3	Turret	
4-3-1	Size of turret	4-17~18
4-3-2	Structure of inside turret	4-19~20
4-4	Oil pressure	
4-4-1	Oil pressure unit	4-21~22
4-4-2	Hydraulic circuit	4-23
4-4-3	Adjustment of hydraulic valve and other kinds of pressure parts.	4-24~25
4-5	Hydraulic chuck capacity	4-26~28
5	Panel	
5-1	Panel mark	5-1~2
5-2	Key name on Panel	5-3

6	Operation	
6-1	Power ON & OFF	6-1
6-2	Manual runs	6-2
6-2-1	Rapid feed	6-2
6-2-2	Cutting feed	6-3
6-2-3	Hand-wheel feed	6-4
6-2-4	Turret positioning	6-5
	(1) Turret positioning	6-5
	(2) Conditions of turret positioning	6-5
6-2-5	Spindle start	6-6
	(1) Spindle start	6-6
	(2) Spindle rpm	6-7
	(3) Conditions of spindle start	6-7
6-3	Auto runs	
6-3-1	Auto run starts	6-8
6-3-2	Discontinuing of auto run	6-9
6-3-3	Termination of auto run	6-9
6-3-4	MDI (manual data input) run	6-10
6-3-5	Various switches used during auto run	6-11
	(1) Optional block skip (Block delete)	6-11
	(2) Program check	6-11
	(3) Regulating feed ratio (override)	6-11
	(4) Regulating rapid feed ratio	6-12
	(5) Regulating spindle speed ratio	6-12
6-3-6	Inserting hand-wheel runs during auto run	6-13
	(1) Inserting method	6-13
	(2) Continuing of auto run	6-14
6-3-7	Program stop, Optional stop	6-15
6-4	Program editing	
6-4-1	Program memory	6-16
6-4-2	Program editing	6-16



6-5 Other switches and their designation	
6-5-1 Emergency stop	6-17
6-5-2 Reset	6-17
6-5-3 Locking inside and outside dia. of chuck	6-18
6-5-4 Cutting oil	6-18
6-5-5 Fastening and loosening of chuck	6-19
6-5-6 Front door interlock	6-19~20
7 Alarm signs	
7-1 NC Alarm signs	7-1
7-2 Alarm signs related to motors	7-1
7-2-1 Spindle motor alarm signs	7-1
7-2-2 Non-spindle motor alarm signs (over heat)	7-1
7-3 Reset of alarm signs	7-2
7-4 Alarm signs List	7-3
8 Procedure for production of CNC process program	8-1~2
8-1 Main functions and description of marks (XZUW)	8-3
8-2 Frequent used G functions	8-4~7
8-2-1 Constant cycle speed control	8-8~12
8-2-2 List of G commands	8-13~14
8-3 M functions	8-15~16
8-4 S functions	8-17
8-5 T functions	8-18
8-6 Coordinates setting	8-19~21
8-7 Tool calibrating	8-22~26
9 List of cutting speed	
9-1 List of cutting speed	9-1
9-2 Standard cutting conditions for tungsten carbide tool	9-2~3
9-3 Standard of drill head cutting speed	9-4
9-4 Feed standard for drill head cutting	9-5
10 Program examples	10-1~2
11 Appendix	
11-1 Feed volume and fee times of threading (for reference)	11-1~2
11-2 Error caused by nose radius (R) of tool	11-3
11-3 List of nose radius (R) correction	11-4~9

# **1. Brief outline**







# 1-1 SPECIFICATION


	Model No.		JG-100	JG-200
	Specification			
	Item			
A-0	Processing capacity			
A-1	Max Turning diameter		400mm	670mm
A-2	Standard diameter		200mm	290mm
A-3	Max diameter		200mm	290mm
A-4	Max length		171mm	370mm
B-0	Stroke			
B-1	X-axis stroke		110mm	135mm
B-2	Z-axis stroke		200mm	610mm
C-0	Spindle			
C-1	Rpm of spindle		5000 rpm	3500 rpm
C-2	Variable speed		1	1
C-3	Spindle nose		140mm	A2-8
C-4	Spindle tapered bore		---	75mm 1/20 taper
C-5	Spindle bearing inside dia.		80mm	130mm
C-6	Spindle bore		53mm	86mm
D-0	Tool holder		43mm	52mm
D-1	Turret		8 STA. TURRET	10 STA. TURRET
D-2	Tool installed		8	10
D-3	Outside dia., edge knife handle		□ 20mm	□ 20mm
D-4	Boring tool dia.		φ25mm	φ40mm
E-0	Feed speed			
E-1	Rapid feed		X : 2000mm/min	X : 2000mm/min
			(Automatic)	(Automatic)
			X : 2000mm/min	X : 2400mm/min
			(Automatic)	(Automatic)

	Model No.	JG-100	JG-200
	Specification		
	Item		
E-2	Cutting feed speed	X : 0.001-500mm/rev	X : 0.001-1260mm/rev
		Z : 0.001-500mm/rev	Z : 0.001-1260mm/rev
F-0	Tailstock		
F-1	Stroke of tailstock	130mm	435mm
F-2	Tailstock sleeve dia.	60mm	90mm
F-3	Taper of tailstock	MT. 3	MT. 5
F-4	Tailstock sleeve stroke	75mm	100mm
G-0	Motor		
G-1	Spindle motor	3.5kw / 5.5kw (β6)	7.5kw / 11kw (β12)
G-2	X , Z axis servo motor	X:1.2kw	X:1.8kw
		Z:1.2kw	Z:2.5kw
G-3	Lubricating oil motor	0.75kw	1.5kw
G-4	Cutting oil motor	0.25kw	0.37kw
H-0	Oil tank capacity		
H-1	Cutting oil	40L	40L
H-2	Motor oil tank	200L	200L
I-0	Machine		
I-1	Length	1700mm	1850mm
I-2	Floor space requirement	2280x1700mm	2370x1600mm
I-3	Weight	2500kgs	4300kgs



# 1-2 APPEARANCE AND DIMENSION



JG-100 modle







**JG-100 Model**





# LAYOUT



Unit:mm

## **2. Installation**



---

## 2-1 INSTALLATION

---

As for the installation of machine, it needs to be carefully to do the base in order to have the best exactness of machining.


An example of the base for installing machine as shown in the Fig. 2-1-1 on the next page. Just note that the machine shall be installed according to the processing method for normal base, because the different geology will have a considerable influence.

Generally, the plant's ground is made of concrete, a thickness of 300mm is quite enough to install.


The space for installation of machine should be based on the peripheral device in order that the operator might not touch the other machines or be disturbed by the wall, because it needs to take apart the cover for maintenance, open/close front door for operation, and move the water tank for taking out chips.

In addition, it's needed to clean the surrounding of the machine and also avoided placing the machine under the sunlight or closing to the heating source (heater).

Some parts of machine deformed will cause its exactness getting worse.



**JG-100 MODEL**



JG-200 MODEL

---

## **2-2 CRANING UP MACHINE**

---

**The company didn't provide the ring for hanging machine.**

**Please fix the machine with fork lift and put it down gently in order not to damage machine**

## 2-3 POWER SUPPLY

For installation, please distribute cable line from your factory's power supply to the primary power supply of non-fuse breaker in the electric box of the machine.

As shown in the Fig. 2-1-1, have the cable insert into the upper of electric board, then make it connect with the non-fuse breaker after checking L1, L2, L3. Please use electric wire more than  $14\text{mm}^2(22\text{mm}^2)$  to distribute line.

Besides, it should be bigger than  $14\text{mm}^2$  electric wire as the ground cable and fix it to the bolt of non-fuse breaker. List 2-3-1 is to show the capacitance of power supply needed for each spindle motor.

Capacitance of power supply

AC3 $\phi$

200, 220, 230, 380, 415, 400

460+- 10% 50/60Hz+-1Hz

Unit:KVA

FANUC		
	JG-100	JG200
Spindle motor model	$\beta 6$ 3.5KW / 5.5KW	$\beta 12$ 7.5KW / 11KW
Spindle motor and servo motor	12	16
CNC and Auxiliary device	3	3
Total capacitance	15	19

Capacitance of power supply





## **3. Lubrication**



---

# 3-1 LUBRICATION

---

Before machine running, please follow the indication in Fig. 3-1 and List 3-1-1 to check the lubrication conditions in every part of the machine. From now on, it should be regularly to inspect, lubricate and replace oil according to the list arranged for lubrication.

The following is to indicate the lubrication conditions in every part.

## 1. Lubrication of spindle

Generally it is not necessary to replace and supple the lubricant to the bearing of spindle because it uses the grease. Please contact our technician if the grease should be replaced due to special reason.

## 2. Bearing unit of Ball Screw

X-axis and Z-axis ball screw bearing unit are enforced on lubricating.

## 3. Lubrication of X-axis, Z-axis, each sliding surface and the inside turret.


All of the machine, saddle, surface of slide guide, X-axis, Z-axis ball screws and the inside turret should be lubricated with the lubricating pump at the front leg of machine.

Please check regularly the oil level of the lubricating pump for supplying.



## 4. Gear Box

The gear box is lubricated with oil bath.


Please check, re-supply, replace according to the lubrication schedule.



**JG-100 OIL HOLE**



**JG-100 OIL HOLE**



**JG-200 OIL HOLE**

Mark Name of company	FC10	G68	HL32
Mobil oil	Mobil Velocity oil No. 6	Mobil Velocity oil No. 2	Mobil DTE oil Light
Shell oil	Shell Terrus oil C10	Shell Tonna oil T68	Tercsso 32
Esso Standard oil	Sppinesso 10	Fedis K68	Shell Terrus oil C32
Mitsubishi oil	Diamond Lube R010	Diamond Slideway 68	Diamond Lube R032
Nippon oil	Spinox S10	Uniway 68	FBK oil R32
Kyodo oil	Kyoski MS oil 10	Kyoscki Slidus 68	Kyoscki RIX Turbinc 32
Idcmitsu oil	Dephny Mcchanic oil 10	Daphny Multiway 68C	Daphny Hydraulic Fluid 32
Showa oil	Showa J-H32	Showa A-R68	Showa J-R32
China Petroleum Corp.	Spindle Oil R12	Slideway Oil 68	R32 Circulation Oil 32AW Mineral Oil

Note: Please use the above-suggested oil or same grade oil.

List 3-4 Oil List

Avoid making use of the bad lubricant or bad quality grease.






## **4. Structure of every part and Maintenance**




# 4-1 SPINDLE



## 4-1-1 Structure and maintenance of spindle



JG-100 size of spindle



JG-200 size of spindle



**JG-200 RPM of spindle / Thrust curve**

---


## **4-1-3 Central spindle regulation**

---

### **4-1-3 Central spindle regulation**


The workpiece becomes as a taper after its outer diameter being cut, or the central height of surface is raised when cutting, please parallel the spindle according to the following items. (Refer to the Fig. 4-1-3).

- 1. Install the test rod in the spindle, place the dial gauge on the turret, read the deviating value of needle after the saddle having been moved toward the X-axis.**
- 2. If the deviating value of needle is higher, loosen the screws fixed on the spindle, check the indicator and adjust the bolt to parallel the spindle.**
- 3. Tighten the bolt of spindle after regulated, then move the saddle again and read the deviating value of needle.**



**JG-100 Central spindle regulation**






**JG-200 Central spindle regulation**

## 4-1-4 Confirmation of turret and central height of spindle


After the center of the spindle being set, the center of turret and the central height of spindle should be adjusted according to the following items. (Refer to the Fig. 4-1-4)

1. Take apart the test rod, install the dial gauge on the spindle.
2. Install the round tool holder on the turret.
3. Move the turret toward the X-axis, overlap the round tool holder with the center of spindle.
4. Turn the spindle a round, and get the value of B.C points.
5. According to the item 4-1-3 to move in parallel the spindle for adjusting the value of B.C about  $+0.02\sim+0.04$ .




Confirmation of turret and central height of spindle

# 4-1-5 ADJUSTMENT OF BELT



JG-100 Adjustment of belt



**JG-200 Adjustment of belt**

# 4-2 Tailstock


## 4-2-1 Structure and size of tailstock shaft

Fig. 4-2-1 : Structure and size of tailstock shaft


When taking apart the tailstock shaft, showed as Fig. 4-2-1, just to knock on slightly the attached bars through the rear of the shaft.

At the moment, please note that the taper should not be covered with dust.

Please clean the taper hole with shredded gauze before putting in the shaft.



## JG-100 structure and size of tailstock shaft




**JG-200 structure and size of tailstock shaft**

# 4-2 Tailstock

## 4-2-2 Thrust of shaft of tailstock

Fig. 4-2-2: Relationship between hydraulic pressure and shaft thrust (excluding the lost thrust caused by tube distribution and friction of oil ring.)

Note: When shaft goes forward, the side of hydraulic cylinder covers an area of  $26.7\text{cm}^2$ .




JG-100/200 Thrust of shaft of tailstock

## 4-2 Tailstock

### 4-2-3 Regulation of center of tailstock


If the workpiece becomes a taper when it was processed with the shaft thrust of tailstock, please parallel the shaft of tailstock according to the following items.

1. Use the test rod to show two centers, after installing the dial gauge on the turret, move the turret toward the Z-axis, and read the deviating value of needle.
2. After loosening the fixed screws and bolts, adjust the level direction with the adjusting bolts at the both sides.
3. Tighten the fixed screws and bolts, then check again the deviating value of needle of dial gauge.




JG-100 Regulation of center of tailstock





**JG-100 Regulation of center of tailstock**




**JG-200 Regulation of center of tailstock**


# 4-3 TURRET

## 4-3-1 Size of turret

Size of turret. As to the tool holder, please refer to the cutting tools list.



JG-100 Size of turret




JG-200 Size of turret


# 4-3 TURRET

## 4-3-2 Inner structure of turret

Inner structure of turret



**JG-100 Inner structure of turret**



**JG-200 Inner structure of turret**

---

# 4-4 Oil pressure

---

## 4-4-1 Oil pressure Unit

**Appearance of oil pressure unit used in this machine.**

**Please refer to the Fig. 3-1-1, List 3-1-1 to replace the hydraulic fluid, clean and replace the filter and inside oil tank.**

**Please use the hydraulic fluid as list 3-1-2. The volume of oil tank is 40L. The oil level is showed at the yellow line of oil gauge. In normal condition, the oil level should be between the yellow line and red line. Besides, take apart the tap on the hydraulic pump and drip some fluid before running.**

**Before delivering the machine, the pressure (30Kgf/cm<sup>2</sup>) of hydraulic pump is already adjusted.**






Fig. 4-4-1 Hydraulic Unit



# 4-4-2 Hydraulic circuit

Fig. 4-4-2: Hydraulic circuit, Table 4-4-2: Name and specification (Standard products) of the related parts of Hydraulic circuit.



NO	Name of accessories	Qty	Specification
1	Motor	1	1HP4P56Z3
2	Pump	1	SF-12B
3	Oil filter	1	AB-1162
4	Oil level	1	LS-3B
5	Filter net	1	MF-06
6	Tube check valve	1	CV-03
7	Pressure gauge	1	FTB-Vertical 70KG
8	Gauge connecting	1	BH-5701
9	Cool-wind Aluminum alloy cooler	1	AL606-CA2
10	Oil tank assembly	1	500 x 290 x 170
11	Oil circuit board	1	LIS-025
12	Oil circuit board	1	LIS-008
13	Magnetic valve	1	MD1D-TA 110V
14	Magnetic valve	1	MD1D-RK 110V
15	Magnetic valve	1	MD1D-S3 110V
16	Modular check valve	2	MVR-SP
17	Modular pilot operated check valve	1	MVPP-D-BB
18	Modular throttle	1	MERS-P
19	Modular reducing valve	1	MZ-21-2HL-A
20	Pressure gauge	2	FTB-3271122-Burred 70 kg
21	Modular reducing valve	1	MZ-21-2HL

Customer NO.	1064	Rate	///
Date	Aug 3, 2008	Radius	///
Dept.		Printing color	Same as the machine
Projection		Assembling plant	
Design No.		Drawing No.	TG-100-D4
Designer	Liu, Ping-nan	Edition	Modifier
Drawer		Date	
Proofreader		Approval	
Approval		Model	TG-100
		No.	
		Cause of Modification	

---

## 4-4 OIL PRESSURE

---

### 4-4-3 Adjustment of hydraulic valve and other pressure parts

#### 1. Main pressure programming

Shown as Fig. 4-4-1, use the pressure adjusting bolt of hydraulic pump to set up the main pressure. ( 30Kgf/cm<sup>2</sup> , 426PSI)

The turret of this machine is fixed with the main pressure, please do not change.

#### 2. Chucking capacity programming

Please take use of the reducing valve as Fig. 4-4-2- to adjust the pressure of hydraulic cylinder of chuck.

Turn the hand-wheel clockwise, the chucking capacity will increase, turn the hand-wheel counterclockwise, the chucking capacity will decrease.

Regarding the connection between chucking capacity and programmed pressure, please refer to the Fig. 4-5-1.

#### 3. Adjustment of thrust and speed of tailstock shaft (Special accessories)

Please refer to the Fig. 4-4-2-12, use the reducing valve to adjust the thrust of tailstock shaft.

Turn the handwheel clockwise, the thrust will increase, turn the handwheel counterclockwise, the thrust will decrease.

Besides, Please refer to the Fig. 4-2-2- , the forward/backward speed of tailstock shaft is adjusted with the regulator.

#### 4. Pressure switch of main pressure (special accessories)

This pressure switch is a security device which is for the purpose of stopping machine immediately in order not to damage the machine because of pressure reducing by some reason. Normally, the pressure is set at 20Kgf/cm<sup>2</sup> .

#### 5. Pressure switch of chuck

This pressure switch is a security device which is for the purpose of stopping machine immediately in order not to damage the machine because of chuck pressure reducing by some reason.

To change the setting value of chucking capacity, please change the pressure of pressure switch as well.

<b>No.</b>	<b>Name</b>	<b>Model</b>	<b>Manufacturer</b>
1	Oil tank	30L	KAYABA
2	P□(P port) Reducing valve	MG-02P-03-T-TT	DAIKIN
3	T□(T port)regulating valve	MT-02T-TT	DAIKIN
4	Magnetic (Solenoid)valve	KSO-G02-4CP-30-N-TT	DAIKIN
5	Magnetic (Solenoid) valve	KSO-G02-2DP-30-N-TT	DAIKIN
6	B□(B port) regulating valve	MT-02-4CP-30-N-TT	DAIKIN
7	Magnetic (Solenoid) valve	KSO-G02-4CP-30-N-TT	DAIKIN
8	Pressure switch	CQ88-221	NAGANO KEIKI
9	Magnetic (Solenoid)valve	KSO-G02-2DP-30-N-TT	DAIKIN
10	Shockproof & silent valve	SV-618	ASAMI KIKI
11	Pressure gauge	PF-50D	DAIKIN
12	B□(B port) Pressure reducing valve	MG-02B-03-T-TT	DAIKIN

List 4-4-2     Name and specification of the related parts of oil pressure

---

## **4-5 HYDRAULIC CHUCKING CAPACITY**

---

**The connection among chucking capacity, hydraulic pressure and rpm of spindle.**


**As returning of the spindle will make centrifugal force increased, therefore, the spindle speed should be considered when calculating the chucking capacity.**

**The chucking capacity should be programmed very carefully because it will suddenly drop caused by high speed returning of spindle.**

**To program the chucking capacity, please refer to the curve of chucking capacity, and instruction of chuck made by the manufacturer.**


**List 4-5-1: Manufacturer and specification of chuck and hydraulic cylinder for Ex-series models**

**JG-100 Curve of hydraulic chucking capacity**




主軸回轉速與夾持力之特性曲線

油壓壓力與靜夾持力之關係 (kgf/cm<sup>2</sup>)



主軸回轉速與夾持力之特性曲線



油壓壓力與靜夾持力之關係

JG-200 Curve of hydraulic chucking capacity


















































## **5. Panel**






# 5-1 PANEL MARKS


Panel marks			
	Feed		Spindle counterclockwise
	Rapid feed		Spindle stop
	Feed Speed regulation		Spindle jog
	Rapid feed Speed regulation		Tailstock front, back
	Speed regulation Spindle speed		Tailstock front, back
	Handwheel feed		Tailstock jog
	Chuck		ON (Ready )
	Tighten		Stop, Off, invalid
	Loosen		Cycle start
	Tighten inside diameter		Feed hold
	Tighten outside diameter		Continuous (stepless) variable regulation
	Spindle clockwise		Steady rest (open)

Panel marks			
	Steady rest (close )		Dry run
	Alarm sign		Home
	Cutting oil		Door lock
	Position record		Edit
	Work lamp		Release. Delete
	Chip conveyor belt		Turret position
	Auto-running (memory)		Process release
	Single block		Door close
	Machine lock		Alarm sign home
	Optional stop		Coordinates moved (drift)
	Block skip		Door open, close
	Manual Data input (MDI)		



LOAD







EMG ?




NC READY



HOME



EMG



+X



-X



EMG STOP


FEED HOLD



CYCLE START




TURRET SELECT





MANUAL SPINDLE



RAPID



FEED






## **6. Operation**




## 6-1 POWER ON AND OFF






## 6-2-2 Rapid Feeding





Note: The "~~~~% min" (feed speed) F may be used to select both feeding speeds of "~~~~ Rapid Feed" and "~~~~Feed" before reset to reference points.


## 6-2-3 Feed




## 6-2-4 Handwheel Feed



Press  (Handwheel Feed) of Mode Select Buttons.




First select axis with Handwheel Axis Select Button, then select the X1 ratio with Handwheel Feed Ratio Button.



Handwheel Impulse Generator, feed speed will move in proportion to handwheel Rpm (One handwheel rotation equals to 100 degrees.)

Handwheel feed ratio	One degree	One rotation
× 1	0.001mm	0.10mm
× 10	0.01mm	1.00mm
× 100	0.10mm	10.00mm

## 6-2-5 Turret Positioning




### (2) Conditions of turret positioning

When turret fails to reach desired position, please confirm:

- (i) Has oil pressure reached the designated value?


## 6-2-6 Spindle Start

### (1) Spindle Start



**Note:** Before manual switch of spindle CW or CCW, please first stop spindle, then give command.

## (2) Spindle Rpm



Using Regulate Spindle Speed Ratio Switch to select desired spindle Rpm.

Spindle Rpm will display on CRT.

### (3) Conditions of spindle start

Spindle won't start under the following conditions:

- (i) Emergency stop;
- (ii) During reset movement;
- (iii) Loosen chuck;
- (iv) During program stops or on optional stop;
- (v) Gear ratio is not selected when gear variable is available;
- (vi) When previous door lock was set as a precondition for spindle disable

(Refer to 3-5-6).


Nevertheless, difference may exist when various special appendix are added to this Manual.


## 6-3 Auto Run


### 6-3-1 Auto run starts

Program memory is stored in NC mainframe.


For details, please refer to the Operation Manual published by NC Manufacturer.





Press  (Auto Run) of Mode Select Buttons.





Press Cycle Start Button, Cycle Start Button indicator is on and auto run starts executing.





Execution will begin by one single block when Single Block Execution Button is effective.

**Note:** Single block run is effective only when Mode Select Button is set on  (Auto Run) or  (Manual Data Input).

### 6-3-2 Discontinuing of Auto Run




### 6-3-3 Termination of Auto Run






### 6-3-4 MDI Run



### 6-3-5 Various Switches Used During Auto Run

#### (1) Optional Block Skip

##### Block Delete



Indicator ON: Program containing single block with “/” sign won't execute.

Indicator OFF: Program containing single block with “/” sign will execute.


#### (2) Program check



Indicator ON: Programmed feed speed F is invalid, execution will be based on selected speed by Regulate Feed Speed Ratio Switch. Furthermore, spindle won't rotate.


Indicator OFF: Execution will be based on programmed feed speed F.

#### (3) Regulating feed ratio




Programmed feed speed may be switched within the range of 0~150%. 100% setting equals to F value.

(4) Regulating rapid feed ratio



Rapid feed ratio may be switched among F0, 25%, 50% and 100%.

(5) Regulating spindle speed ratio




Indicator ON: Programmed spindle speed may be regulated within 70~120% range according to switch volume.


Indicator OFF: Switch volume invalid, switch fixed on 100% as programmed F.

## 6-3-6 Inserting Handwheel Run during Auto Run

(1) Inserting method





(2) Continuing of Auto Run



**Note:**

- (i) Please return to previous spindle rotation direction and speed before inserting handwheel run to start machine.
- (ii) Spindle will activate from Stop status and follow inserted handwheel run command. When press Cycle Start Button, spindle will continue rotate in according to the previously programmed command.


### 6-3-7 Program Stop and Optional Stop



Upon completion of single block execution containing M00 or M01 (M01 represents effective optional stop), Program Stop Button indicator will be ON and program stops.



Single block will be on stop status when M00 or M01 is executed. To continue executing the program, please resume to previous status with applicable M command.




Press Cycle Start Button, program will continue executing.

# 6-4 Program Editing

## 6-4-1 Program memory

Please refer to official FANUC Operation Manual.

## 6-4-2 Program editing




---

## 6-5 Other Switches and Their Designation

---

### 6-5-1 Emergency Stop



RESET----Press Emergency Stop to activate.  
Rotate RESET switch in arrow direction to relief  
Emergency Stop.

**Note:** To reset the machine, press Ready after release of Emergency Stop. It is also essential to execute resetting reference points since displacement of each axis has been caused by Emergency Stop.

### 6-5-2 Reset





Press Reset button on MDI panel to execute resetting.



### 6-5-3 Locking Inside and Outside Diameters of Chuck


M10: Select chuck locking direction.  
M11: Use MDI mode to command switch.  
Don't execute program during Auto Run.

### 6-5-4 Cutting Oil




Cutting Oil will hold during Program Stop, Optional Stop,  
Test Run and Program Check.

### 6-5-5 Fastening and Loosening of Chuck




Step on pedal switch to control open and close of chuck claws.

If the chuck is open, one step on the pedal switch to close chuck, step again, the chuck will open. Chuck lock indicator will be ON when chuck is on close status.



### 6-5-6 Front Door Locking



Switch to engage and disengage front door lock.




Front door lock disengaged.




Front door lock engaged.

Turn the additional key attached to this switch to computer administrator for proper care.

**6-5-7 Spindle Motor Load Chart (Special Appendix)**

	Represents Spindle Motor load value.
---	--------------------------------------

**6-5-8 Alarm Sign Indicator**

	In case of alarming condition, this indicator will be ON.
--	---

## **7. Handling of Alarm Signs**



## **7-1 NC Alarm Signs**

Alarm signs status displaying on CRT can be processed and resolved in accordance with description stated in the officially published operation manual of NC manufacturer.

## **7-2 Alarm Signs Related to Motors**

### **7-2-1 Spindle Motor**

Please refer to alarm signs instructions attached on spindle motor and handle in accordance with description stated in the officially published operation manual of NC manufacturer.

### **7-2-2 Non-Spindle Motor**

For over heat of auxiliary motor, please check thermal relay in the electric box.

## **7-3 Reset of Alarm Sign**



When Alarm Sign Reset Button indicator is ON, first eliminate cause of alarm sign, then, press Alarm Sign Reset Button to lift alarm sign.

When machine is on Feed Hold status, NC Reset Button on MDI panel should be pressed before press Alarm Sign Reset Button to lift alarm sign.


**Note:** To silence the buzz sound issuing upon failure occur, first press Alarm Sign Reset Button and press this button again after eliminating failure cause to lift alarm sign.

### Alarm List

Alarm No.	Description	Remark
1000	Tool No. > Reset First input Home Tool, then Rest.	
1001	Soft Limit 2 Over Travel X/Z axes travel CCW.	
1002	Soft Limit 3 Over Travel X/Z axes travel CCW.	
1003	Turret Mis-Index Check tool number for accuracy.	
1004	Soft Limit 4 Over Travel X/Z axes travel CCW.	
1005	Door Not Close Close front door.	
1006	SP#1Chuck Unclamp Use pedal to close chuck.	
1007	Chuck End Stroke Check to confirm that chuck is clamping tight.	
1008	X-Axis Not Home X Use Home mode to reset X axis.	
1009	X, Z Axis Not Home X/Z Use Home mode to reset X/Z axis.	
10011	Turret Not Orientated Orientate turret clamp by manual or compulsory mode.	
10016	Spindle #1 Amplifier Detect Error Please contact manufacturer for consultation.	
10017	Hydraulic Fail Check if Oil Pressure Motor is running or Pressure Valve switch is normal.	









# **8. Procedure for Production of CNC Process Program**



This manual aims to provide fundamentals and smooth operating of regular NC machine. For those who want to produce general process program, this manual may be utilized as a useful guide. It is advised that users should refer to the operation manual published by NC assembler and manufacturer for more advanced processing program or if detailed description is needed.





# 8-1 Main Functions and Description of Marks


## (XZUW)

X or Z represents a command mark of absolute value. In a coordinates, they are used to register code numbers of X axis and Z axis respectively (X axis is a diameter command).

U and W are marks used for relative command.

U→travel distance of X axis.

W→travel distance of Z axis. / Registered code number



When claw end face and center of spindle are used as origin points, all range covered by  $\oplus\ominus$  of X and Z are shown as drawing.

Nevertheless, when current position of U and W is (0,0),  $\oplus\ominus$  should be determined by turret direction.

- X and U are commanded by diameter value.
- Both absolute and relative values may combined in the same program.
- General or regular lathe should adopt relative value.

## 8-2 Frequent used G functions

G00

When used for coordination (Rapid feed)

May also be used when M.S.T. functions are in use.

Attention should be paid to interference from tail stock, material, chuck and tool. (Travel paths are not necessarily linear.)

G00 X\_\_Z\_\_

G00 U\_\_W\_\_

G00 M\_\_

G01

Linear travel under F speed command.

G01 X\_\_F0.3

↳ Feed volume 0.3 mm/rev

G01 X\_\_Z\_\_F\_\_

When X, Z or U, W exists in the same single block, a taper shape may be formed. Special functions like chamfer and fillet (R) are also included to facilitate processing production. In processing of fillet (R) (R=designated radius)

G01 Z\_\_R\_\_ from Z direction to X direction

G01 Z\_\_R\_\_ from X direction to Z direction

In processing of chamfer (C=designated radius)

G01 Z\_\_C

G01 X\_\_C

C is determined by direction mark of cutting axis.

Example: Direction marks of R, C become  $\oplus$  when cutting axis travels in Z direction.

G02

Fillet cutting (in CW direction)

G02X(U)\_\_Z(W)\_\_R\_\_F\_\_

or I\_\_K\_\_F\_\_

G03

Fillet cutting (in CCW direction)

G03X (U) \_\_\_ Z (W) \_\_\_ R \_\_\_ F \_\_\_  
or I \_\_\_ K \_\_\_ F \_\_\_


X.Z.: End position of fillet

U.W.: Distance between starting point to end point of fillet

R.: Radius of fillet

I.K.: Distance between starting point to center of fillet

X axis/end point/designated diameter/starting point/Z axis



G04

Dwell

G04 X (t)

Upon completion of a single block execution, a pause of (t) seconds should be followed by the subsequent single block.

Thread Cutting

G32


G32 X \_\_\_ Z \_\_\_ F \_\_\_

F: Lead directly designate for thread cutting



**G50****Coordinate Setting****G50 X\_\_ Z\_\_**

- ◆ Determined by the coordinates on which tools travel under absolute value command. This is not the actual travel command. Notify the Position between  $X=0, Z=0$  and tool tip as indicated in the following drawing to NC device.
- ◆ Input the size calculating from tool tip, starting point, to  $X=0, Z=0$ .
- ◆ Operator needs to find out X, Z starting position of G50 manually before begin processing (Programmed X, Z coordinates of G50 corresponds with that of tool tip.)
- ◆ Normally,  $X=0$  is spindle center position.  
 $Z=0$  may be set at any position, provided that  
 $Z=0$  position is normally set at chuck end face, material left end face or right end face.



G92

Thread Cutting Cycle

G92 X \_\_\_ Z \_\_\_ R \_\_\_ F \_\_\_


X: X coordinates at end point

Z: Z coordinates at end point

R: Incremental value of X axis

F: Threading lead

R value is not needed in linear threading operation.



G96	G97
-----	-----

Constant Cycle Speed Control

For machine equipped with DC motor or AC variable motor to drive spindle, G96 stands for power ON of constant cycle speed control, while G97 stands for constant revolving speed control.

G96 S200 cycle speed 200m/min

G97 S200 revolution speed 200min<sup>-1</sup>

### 8-2-1 Constant Cycle Speed Control


Constant cycle speed control means to revolve spindle under acquired accurate cycle speed status by calculating spindle revolve speed with variable cycle speed F of working part's position and send out corresponding voltage to spindle control part when give cycle speed command (relative speed between tool and working part.)

Unit for calculating cycle speed are as follows:

Input unit	Cycle speed unit
Metric	m/min
English	Feet/min

G Code	Meaning	Unit
G96	Execution of constant cycle speed control	m/min, feet/min
G97	Designate spindle revolution speed	Min <sup>-1</sup>

When executing constant cycle speed control, coordinates of working part must be set by revolving back to X axis (X=0).



## 1. Clamping on Max. Rpm of Spindle

Max. Rpm of spindle may be controlled by giving  $\text{min}^{-1}$  command while conducting constant cycle speed control of G50S

G50S\_\_\_;

Clamping on max. Rpm of spindle will activate when spindle revolution speed exceeds the above programmed speed.

## 2. Rapid feed speed (G00)

When G00 is used to command rapid feed speed, constant cycle speed control may not only be calculated in accordance with tool position changes but also coordinates with distance changes between starting point and end point. This is the calculation of rapid feed speed before non-cutting operation.

### **Note:**

(1) When power ON, unsetting status of spindle max. Revolution speed equals to unclamping status.

(2) Clamping status applies only to G96 mode.

(3)  $G50S0 \cdot \text{min}^{-1}$  represents the meaning of clamping.

(4) The designated value in G96 mode will be saved in G97 mode, and will be auto reset when operation returns to G96 mode.

G96S50; (50m/m or 50 feet/min)

G97S1000; ( $1000\text{min}^{-1}$ )

G96X1000; (50m/mm or 50 feet/min)

(5) Cycle speed commanded by control cycle speed control designates cycle speed of program path not for program path after offset.

(6) When clamping is effective, machine will calculate constant cycle speed bases on X axis coordinates changes although there is no movement.

(7) Constant cycle speed control is still valid during thread cutting. Constant cycle speed control under G97 command becomes invalid during linear or slant thread cutting. Nevertheless, it has no effect on servo reaction and the changes of spindle revolution speed.

(8) Although it is meaningless, G96 command may be given during G98 (feed/min) command.

(9) Final revolution speed of G96 will be based on S ( $\text{min}^{-1}$ ) of G97 code if S ( $\text{min}^{-1}$ ) is not adopted by G97 upon transfer of G96 to G97.

N111G97S800;  $800\text{min}^{-1}$

N222G96S100;  $100\text{m/min}$

N333G97; Xmin

X is revolving speed  $X\text{min}^{-1}$  of the previous single block before N333.

During G97→G96 transfer, S value in G96 is effective.

S=0m/min (feet/min) when no S value is designated.




Fig. 3-2-1 Example of Program Embodiment

(Diameter Commands)

```

N8  G00  X1000.  Z1400.  ;
N9          T0303 ;
N11      X400.  Z1050.  ;
N12  G50          S3000 ; (Designation of max. revolve speed)
N13  G96          S200  ; (Cycle speed 200m/min)
N14  G01          Z700.  F1000 ;
N15      X600.  Z400.  ;
N16          Z...  ;

```

NC calculates designated cycle speed with programmed X coordinates position.

As such, NC has an additional way of calculation besides using X value of path after offset. As shown in the above drawing, end point of N15 is not the center of turret but the front end of turret, e.g., cycle speed of  $\phi 600$  equals 200m/min.

Calculation should be based on absolute when X value is negative.

**Note:** T function should be commanded with a four-digit when constant cycle speed function is available.




Figure 3-2-2 Relations between spindle Rpm and cycle speed

## 8-2-2 List of G Code

**B: Standard    O: Special function**

Standard G		Function	Classification
▶ G00	01	Rapid coordinating	B
G01		Linear interpolation	B
G02		Fillet interpolation (CW)	B
G03		Fillet interpolation (CCW)	B
G04	00	Dwell	B
G10		Setting offset volume	B
G20	06	Input of English system	B
G21		Input of metric system	B
G27	00	Testing of reference point reset	B
G28		Reset of reference point	B
G32	01	Thread cutting	B
G50	00	Thread cutting	B
G68	04	Turret mirror image function ON	O
▶ G69		Cancel mirror image function	B
G90	01	Cutting cycle A	B
G92		Thread cutting cycle	B
G94		Cutting cycle B	B
G96	02	Constant cycle speed control	O
▶ G97		Cancel constant cycle speed control	O
G98	05	Feed/min	B
▶ G99		Feed/rev.	B

### Note:

1. All G codes with “▶” sign indicate status of G codes when power ON.
2. G codes belong to “00” group represent non-patterned G codes which only effect when single block code is activated.
3. Alarm sign (No.010) will be issued when G code not included in the list is given.
4. An unlimited number of G codes may be given in a single block if those codes don't belong to the same group. When two G codes are given in a single block, only the latter given G code is effective.
5. Each G codes may be indicated by its group number.



## 8-3 M Functions

All M functions of this machine are listed as follows. Please be noticed that M functions of other machines with different specifications are excluded.

M00	Program Stop
M01	Program Optional Stop
M02	End of Program
M03	Spindle CW
M04	Spindle CCW
M05	Spindle Stop
M08	Coolant ON
M09	Coolant OFF
M10	Spindle#1 Chuck Clamp
M11	Spindle#1 Chuck Unclamp
M12	Quill OUT
M13	Quill IN
M17	Auto Door Close
M18	Auto Door Open
M21	Door Interlock Bypass ON
M22	Door Interlock Bypass OFF
M23	Chamfering ON
M24	Chamfering OFF
M30	Program Rewind
M31	Spindle#1 Chuck Bypass ON
M32	Spindle#1 Chuck Bypass OFF
M33	Block Skip ON
M34	Block Skip OFF
M37	Chip Conveyor CW
M38	Chip Conveyor Stop
M40	Low Gear Change
M41	Middle Gear Change
M42	High Gear Change
M47	Chuck Soft Limit 2 Valid
M48	Tail Stock Soft Limit 3 Valid
M49	Soft Limit 2&3 Invalid
M51	Error Detect OFF

M52	Error Detect ON
M55	Tail Stock Clamp
M56	Tail Stock Unclamp
M57	Spindle#1 Air Blow ON
M58	Spindle#1 Air Blow OFF
M71	Mirror Image X ON
M97	Parts Counter
M98	Calling of Subprogram
M99	Main Program Return

**Note:**

1. Classification B and O in the list stand for standard specification and special function respectively.
2. M02 and M03 may be used for number counting in machine equipped with various counter and processing completion lamp (special specification.)
3. When press Reset button of M02 or M03, machine will return to program ER.

## 8-4 S Functions

### S4 Codes

G97 S1500



Rpm. may be directly commanded by a four-digit figure.  
Speed at this command is 1500 rev. (without constant cycle speed control function.)

G50 S1400



Max. Rpm. is clamped on 1400 rev. when constant cycle speed control function is available.

G96 S120




To execute 120m/min constant cycle speed control.

# 8-15 T Functions

## T4 Codes

### T01 Tool



#### 1. Tool offset number

A total of nine sets of number are used to offset displacement or wearing of tool.

Max. value:  $\pm 999.999$


Offset may be set for each individual number (OFX, OFZ).

Offset	OFX (X Offset)	OFZ (Z Offset)
1	0.010	0.020
2	0.000	0.000
3	3	3
9	0.100	1.340

### T0000

Offset number starts with "00" means cancel offset.

## 8-6 Coordinates Setting



Example: Tool Installation

No.1 Outside diameter tool (base tool)

No.2 Outside diameter tool

No.3 Inside diameter tool

No.4 Inside diameter tool


No.5 Drill head

※ All values of X axis (direction) are diameter values.

### 1. Auto Coordinates Setting

Coordinates shown in the following drawing may be set by auto coordinates setting for manual or auto reference point reset.

Spindle end face



PRM \* \* \* = 350000

PRM \* \* \* = 450000

Upon completion of auto coordinates setting, first execute reference point reset (the result will be the same as executing G50×350Z 450 EDB), then execute pre-set POS (indicating position).

## 2. Drift of Working Coordinates


In actual practice, it is necessary to conduct drift of parts clamping coordinates, as shown in the preceding page, after tool installation.

Select base tool No.1 for optional surface cutting while conducting actual measuring by disengaging from spindle under the condition of Z axis not moving.

### Example:

When program origin, as shown in the following drawing, is 60mm away from left side, position of cutting end face is 62mm from left side, which is expressed as Z2.0.


When distance to program origin is 60mm, equation equals to 0.2mm should be added for actual measuring value of 62mm; minus 1mm for 59mm.



Operation procedures are shown as follows:

1. Repeatedly press OFFSET/SETTING button several times until displaying of OFFSET screen.
2. Press Select Chapter Button to display workpiece Drift screen.

Workpiece Drift	
(Drift Value)	(Measuring Value)
X 0	X
Z	Z
Current Position (Relative Coordinates)	
U	W
【       】【Workpiece Drift】【       】【       】【(Operation)】	



Move cursor to value corresponding to Z, key-in 2.0 then press Enter.  
(Key-in -1.0 if measuring value is -1m/m.)

Workpiece Drift	
(Drift Value)	(Measuring Value)
X 0	X
Z	Z
Current Position (Relative Coordinates)	
U	W
【       】【       】【       】【 +Enter 】【 +Enter 】	



**Note:** Make sure that drift volume for X axis is zero.

When drift volume for X axis is not zero, move cursor to value corresponding to X, then, press Enter.

Upon completion of reference point reset, both drifted coordinates setting and current position pre-setting are also completed.


Value may be input by press Enter after moving cursor to correspond with drift volume of X or Z.

Before press Enter, previous drift volume should be added to input value.

## 8-7 Tool Calibrating

Select base tool No.1 to execute optional outside diameter cutting. Disengage working part with X axis not moving. Stop spindle, measure outside diameter value.

**Example:** When outside diameter is 50m/m.




Operation sequence should be as follows:

- (1) Press functions key—Offset/Setting to call out offset screen.
- (2) Press Offset key

Offset/Setting



【 Offset 】 【 Setting 】 【     】 【     】 【 Operation 】






(3) Press **Shape** key

(4) Move cursor to Offset number



(5) Press **Operation** key




Input X50, press No. Search, X value of **Offset No.1** will automatically count in.

**Note:** Z value of Offset No.1 is zero.


When Z value is not zero, first move cursor to correspond with Z value and input 0, then press **Enter** to change value to 0.

## 1. Calibrating of outside diameter tool




- (1) Cut outside diameter face with calibrated base tool, and use No.2 tool to conduct test.  
Do not move X axis.  
Move cursor on Operation Sequence (5) screen to call out Offset number.  
Input X50, press soft key—   
Under Auto Coordinates setting, display offset to X movement of pre-set coordinates.
- (2) Drift cutting end face with parts coordinates, conduct test with No.2 tool.  
Do not move Z axis.  
Always match value with cursor.  
First input Z2.0, then press soft key—   
Input offset volume displayed by Z movement of base tool No.1.

## 2. Calibrating of inside diameter tool



- (1) Cut inside diameter face with calibrated base tool No.3, and disengage with X axis not moving.  
Stop spindle and conduct inside diameter value test.  
Move cursor on Operation Sequence (5) screen to call out Offset number.  
Input X30.0, press soft key—**Test**.  
Under Auto Coordinates setting, display offset to X movement of pre-set coordinates.
- (2) Drift cutting end face with parts coordinates, conduct test with No.3 tool.  
Do not move Z axis.  
Always call out offset number with cursor.  
First input Z2.0, then press soft key—**Test**.  
Input offset volume displayed by Z movement of base tool No.1.

### 3. Inside tool B



- (1) Cut inside diameter face with inside diameter tool, and use No.4 tool to conduct test.

Do not move X axis.

Move cursor to call out offset number.

Input X30.0, press soft key—.

Under Auto Coordinates setting, display offset to X movement of pre-set coordinates.

- (2) Drift cutting end face with parts coordinates, conduct test with No.4 tool.

Do not move Z axis.

Always call out offset number with cursor.

First input Z2.0, then press soft key—.


Offset value to Z movement of base tool No.1 is now displaying.



## **9. List of Cutting Speed**



# 9-1 List of Cutting Speed



$$V = \frac{\pi \cdot D \cdot N}{1000}$$

V = Cutting speed      m/min

D = Workpiece diameter      m/min

N = Revolution speed      min<sup>-1</sup>



## 9-2 Standard Cutting Conditions for Tungsten Carbide Tool

Material Name	Material Mark	Feed: 0.2~0.5mm/rev		Feed: 0.05~0.2mm/rev	
		Cutting Speed Vm/min	cutting tool	Cutting Speed Vm/min	Cutting tool
Carbon steel for mechanical structure	S20C ~ 30C	140 ~ 180	P20	150 ~ 230	P10
	S35C ~ 45C	100 ~ 140		120 ~ 190	
	S50C	70 ~ 100		80 ~ 140	
Polished steel bar	S20CD ~ S50CD	70 ~ 100		80 ~ 140	
Steel alloys	SNC1 ~ SNC3	70 ~ 100	P10	80 ~ 140	M10
Stainless steel	SUS24	60 ~ 100	M10	80 ~ 140	
	SUS27 ~ SUS33	40 ~ 70	M20	80 ~ 140	
Heat-resistance steel	SEH1 ~ SEH5	40 ~ 70	P40	70 ~ 100	
Forged carbon steel	SF40 ~ SF50	140 ~ 180	P20	150 ~ 230	P10
	SF55 ~ SF60	100 ~ 140	P30	120 ~ 190	
Cast steel	SC42 ~ SC49	100 ~ 120	P20	120 ~ 180	P10
Cast steel alloys	SCA1 ~ SCA23	60 ~ 100		70 ~ 120	
	SCA31	50 ~ 80		70 ~ 100	
	SCA41 ~ SCA52	60 ~ 100		70 ~ 120	
Stainless cast steel	SCS1 ~ SCS15	50 ~ 80	M20	70 ~ 140	M20
Heat-resistance cast steel	SCH1 ~ SCH2	60 ~ 90		70 ~ 120	
	SCH11 ~ SCH13	50 ~ 80		60 ~ 100	

Material Name	Material Mark	Feed: 0.2~0.5mm/rev		Feed: 0.05~0.2mm/rev	
		Cutting Speed Vm/min	cutting tool	Cutting Speed Vm/min	Cutting tool
Gray cast iron	FC20	70 ~ 110	K10	80 ~ 130	K10
	FC25 ~ FC30	60 ~ 100		80 ~ 130	
Bronze castings	BC2 ~ BC7	100 ~ 200		200 ~ 350	
Aluminum	AC3A ~ F	200 ~ 400		300 ~ 500	
Alloy castings	AC4A-F-AC7B-T4	800 ~ 900		800 ~ 1200	
Synthetic leather, Wood		300 ~ 600	K10 K20	350 ~ 600	K10 K20

## 9-3 Standards of Drill Head Cutting Speed

Material		Cutting Speed (m/min)
Carbon steel	below 0.4C	24 ~ 33
	0.4C ~ 0.7C	18 ~ 24
	above 0.7C	12 ~ 18
Steel alloys	60kg/mm <sup>2</sup>	15 ~ 18
	60 ~ 80kg/mm <sup>2</sup>	9 ~ 15
	80kg/mm <sup>2</sup>	5 ~ 9
Stainless steel	マルテンサイト	10 ~ 20
	フェライト	15 ~ 18
	オーステナイト	5 ~ 15
Manganese steel	12 ~ 14%	3.5 ~ 4.5
Plastics		30 ~ 90

Material	Cutting Speed (m/min)
Aluminum; Aluminum alloys	60 ~ 90
Bronze with average tension-resistance	45 ~ 75
	22.5 ~ 45
Mg; Mg alloys	60 ~ 120
Rapid cutting metals	9 ~ 15
Nickel steel	9 ~ 15
Zinc alloys	45 ~ 80
Brass	45 ~ 90
Gold	60 ~ 75
Cutting steel	8 ~ 22
Cast alloys	6 ~ 9


## 9-4 Feed Standard for Drill Head Cutting

Drill head diameter	Feed (mm/rev)	
	General steel	Stainless steel
1.6 ~ 3	0.05 ~ 0.06	0.05 ~ 0.08
3 ~ 4	0.05 ~ 0.1	0.06 ~ 0.15
4 ~ 5.5	0.08 ~ 0.15	0.1 ~ 0.23
5.5 ~ 8	0.1 ~ 0.2	0.13 ~ 0.3
8 ~ 11	0.15 ~ 0.25	0.19 ~ 0.35
11 ~ 14.5	0.2 ~ 0.3	0.25 ~ 0.45
14.5 ~ 17.5	0.23 ~ 0.33	0.28 ~ 0.6
17.5 ~ 20.5	0.25 ~ 0.36	0.31 ~ 0.53
20.5 ~ 24	0.28 ~ 0.38	0.34 ~ 0.56
24 ~ 28.5	0.3 ~ 0.4	0.38 ~ 0.6
28.5 ~ 38	0.35 ~ 0.45	0.44 ~ 0.68
38 以上	0.4 ~ 0.5	0.5 ~ 0.7



# **10. Program Examples**





T1: Outside diameter rough cutting  
 T2: Outside diameter fine cutting  
 T3: Outside diameter cutting slot  
 T4: Outside diameter threading  
 Material: S45C

```

No.1  G00  X100.0  Z50.0 ;
      G50  S1800 ;
      G96  S140  M03  T0101 ;
      X35.0  Z2.0  T01  M08 ;
      G01  Z-66.9  F0.4 ;
      X44.0 ;
      G00  Z2.0 ;
      X23.5 ;
      G01  X30.5  Z-1.5 ;
      Z-18.0 ;
      X34.5  Z-43.0 ;
      G02  X33.751  Z-66.9  R20.0 ;
      G01  X44.0 ;
      G00  X100.0  Z50.0  T00 ;
      M01 ;
  
```



No.2	G00	X100.0 Z50.0 ;
	G96	S200 M03 T0202 ;
		X23.0 Z2.0 ;
	G01	X30.0 Z- 1.5 F0.15 ;
		Z- 18.0 ;
		X34.0 Z- 43.0 F01 ;
	G02	X34.0 Z- 67.0 R20.0 ;
	G01	X39.0 ;
		X41.0 Z- 68.0 ;
		X44.0 ;
	G00	X100.0 Z50.0 T00 ;
		M01 ;
No.3	G00	X100.0 Z50.0 ;
	G96	S130 M03 T0303 ;
		X34.0 Z- 18.0 ;
	G01	X26.0 F0.08 ;
	G04	U0.1 ;
	G01	X34.0 F0.5 ;
	G00	X100.0 Z50.0 T00 ;
		M0 ; 1
No.4	G00	X100.0 Z50.0 ;
	G97	S1300 M03 T0404 ;
		40.0 Z2.0 ;
	G92	X29.4 Z- 16.0 F1.0 ;
		X29.0 ;
		X28.8 ;
		X28.7 ;
		G00
		M05 ;
		M30 ;


**Note:** Conduct parts drift setting with auto coordinates when G50 is replaced by G00.

# 11. Appendix



# 11-1 Feed Volume and Feed Times of Threading

Example of male thread



P: Thread pitch  
 D: Outside diameter  
 H: Thread height  
 r: Fillet at thread bottom

Metric system

P	1.00	1.25	1.50	1.75	2.00	2.50	3.00	3.50	4.00	
H	0.65	0.81	0.97	1.13	1.30	1.62	1.95	2.27	2.60	
r	0.11	0.14	0.16	0.19	0.22	0.27	0.33	0.38	0.43	
Cutting times and feed volume	1	0.30	0.30	0.35	0.40	0.40	0.40	0.40	0.40	0.40
	2	0.20	0.20	0.20	0.25	0.15	0.30	0.30	0.30	0.30
	3	0.10	0.20	0.20	0.25	0.25	0.25	0.25	0.25	0.30
	4	0.05	0.06	0.10	0.10	0.20	0.25	0.25	0.25	0.25
	5		0.05	0.07	0.08	0.10	0.15	0.25	0.25	0.25
	6			0.05	0.05	0.05	0.15	0.20	0.20	0.25
	7					0.05	0.07	0.10	0.20	0.25
	8						0.05	0.10	0.15	0.20
	9							0.05	0.15	0.20
	10							0.05	0.07	0.10
	11								0.05	0.05
	12									0.05

Whitworth thread


Thread number	24	20	18	16	14	12	10	8	6	
P	1.058	1.270	1.411	1.588	1.814	2.117	2.540	3.175	4.233	
H	0.68	0.81	0.90	1.02	1.16	1.36	1.63	2.03	2.71	
r	0.15	0.17	0.19	0.22	0.25	0.29	0.35	0.44	0.58	
Cutting times and feed volume	1	0.30	0.30	0.35	0.35	0.40	0.40	0.40	0.40	0.40
	2	0.20	0.20	0.20	0.25	0.25	0.25	0.30	0.30	0.30
	3	0.10	0.20	0.20	0.20	0.25	0.25	0.25	0.25	0.30
	4	0.08	0.06	0.10	0.10	0.10	0.20	0.25	0.25	0.25
	5		0.05	0.05	0.07	0.10	0.15	0.15	0.25	0.25
	6				0.05	0.06	0.06	0.15	0.20	0.25
	7						0.05	0.08	0.15	0.25
	8							0.05	0.10	0.20
	9								0.08	0.20
	10								0.05	0.10
	11									0.10
	12									0.06
	13									0.05

# 11-2 Error Caused by Nose Radius (R) of Tool

## (Arc Cutting)

Fillet cutting with tool nose set as shown in right Figure usually causes the same error.

To execute actual cutting path and the sizes specified in the drawing, please follow the procedures below:





(1) Inside cutting

Programmed arc radius(R) = arc radius (R') specified in the drawing – nose radius (r)

(2) Outside cutting

Programmed arc radius(R) = arc radius (R') specified in the drawing + nose radius (r)



(1) Inside cutting

$$R + r = R'$$

$$R = R' - r$$

(2) Outside cutting

$$R - r = R'$$

$$R = R' + r$$

## 11-3 List of Nose Radius (R) Correction

Application of the list should be based on min. setting unit of the machine.

$\theta \backslash R$		List 1-1						
		0.2	0.4	0.5	0.6	0.8	1.0	1.2
1°	X	.0035	.0069	.0087	.0104	.0138	.0173	.0208
	Z	.1983	.3965	.4956	.5948	.7930	.9913	1.1895
1° 30'	X	.0052	.0103	.0129	.0155	.0207	.0258	.0310
	Z	.1974	.3948	.4935	.5921	.7895	.9868	1.1843
2°	X	.0069	.0137	.0172	.0206	.0274	.0343	.0412
	Z	.1965	.3930	.4913	.5895	.7860	.9825	1.1791
2° 30'	X	.0085	.0171	.0214	.0256	.0342	.0427	.0512
	Z	.1956	.3913	.4891	.5869	.7825	.9782	1.1738
3°	X	.0102	.0204	.0255	.0306	.0408	.0510	.0612
	Z	.1948	.3895	.4869	.5843	.7791	.9738	1.1686
3° 30'	X	.0119	.0237	.0296	.0356	.0474	.0593	.0712
	Z	.1939	.3878	.4847	.5817	.7756	.9694	1.1633
4°	X	.0135	.0270	.0337	.0405	.0540	.0675	.0810
	Z	.1930	.3860	.4825	.5790	.7721	.9651	1.1581
4° 30'	X	.0151	.0302	.0378	.0454	.0605	.0756	.0907
	Z	.1921	.3843	.4804	.5764	.7686	.9607	1.1529
5°	X	.0167	.0335	.0418	.0502	.0669	.0837	.1004
	Z	.1913	.3825	.4782	.5738	.7651	.9222	1.1476
5° 30'	X	.0183	.0367	.0458	.0550	.0733	.0917	.1100
	Z	.1904	.3808	.4760	.5712	.7616	.9520	1.1424
6°	X	.0199	.0398	.0498	.0598	.0797	.0996	.1195
	Z	.1895	.3790	.4738	.5686	.7581	.9476	1.1371
6° 30'	X	.0215	.0430	.0537	.0645	.0860	.1075	.1290
	Z	.1886	.3773	.4716	.5659	.7546	.9432	1.1319
7°	X	.0231	.0461	.0576	.0692	.0922	.1153	.1383
	Z	.1878	.3755	.4694	.5633	.7511	.9388	1.1266
7° 30'	X	.0246	.0492	.0615	.0738	.0984	.1230	.1476
	Z	.1869	.3738	.4672	.5607	.7476	.9345	1.1213

$\theta \backslash R$								List 1-2	
		0.2	0.4	0.5	0.6	0.8	1.0	1.2	
8°	X	.0261	.0523	.0654	.0784	.1046	.1307	.1569	
	Z	.1860	.3720	.4650	.5580	.7441	.9301	1.1161	
8° 30'	X	.0277	.0553	.0692	.0830	.1107	.1383	.1660	
	Z	.1851	.3703	.4628	.5554	.7405	.9257	1.1108	
9°	X	.0292	.0584	.0730	.0876	.1167	.1459	.1751	
	Z	.1843	.3685	.4606	.5528	.7370	.9213	1.1056	
9° 30'	X	.0307	.0614	.0767	.0921	.1227	.1534	.1841	
	Z	.1834	.3668	.4585	.5501	.7335	.9169	1.1003	
10°	X	.0322	.0644	.0805	.0965	.1287	.1609	.1931	
	Z	.1825	.3650	.4563	.5475	.7300	.9125	1.0950	
10° 30'	X	.0337	.0673	.0842	.1010	.1346	.1683	.2020	
	Z	.1816	.3632	.4541	.5449	.7265	.9081	1.0897	
11°	X	.0351	.0703	.0878	.1054	.1405	.1757	.2108	
	Z	.1807	.3615	.4519	.5422	.7230	.9037	1.0845	
11° 30'	X	.0366	.0732	.0915	.1098	.1464	.1830	.2196	
	Z	.1799	.3597	.4497	.5396	.7194	.8993	1.0792	
12°	X	.0380	.0761	.0951	.1141	.1522	.1902	.2283	
	Z	.1790	.3580	.4474	.5369	.7159	.8949	1.0739	
12° 30'	X	.0395	.0790	.0987	.1184	.1579	.1974	.2369	
	Z	.1781	.3562	.4452	.5343	.7124	.8905	1.0686	
13°	X	.0409	.0818	.1023	.1227	.1637	.2046	.2455	
	Z	.1772	.3544	.4430	.5316	.7089	.8861	1.0633	
13° 30'	X	.0423	.0847	.1058	.1270	.1693	.2117	.2540	
	Z	.1763	.3527	.4408	.5290	.7053	.8816	1.0580	
14°	X	.0437	.0875	.1094	.1312	.1750	.2187	.2625	
	Z	.1754	.3509	.4386	.5263	.7018	.8772	1.0527	
14° 30'	X	.0451	.0903	.1129	.1354	.1806	.2257	.2709	
	Z	.1746	.3491	.4364	.5237	.6982	.8728	1.0473	
15°	X	.0465	.0931	.1163	.1396	.1861	.2327	.2792	
	Z	.1737	.3473	.4342	.5210	.6947	.8683	1.0420	
15° 30'	X	.0479	.0958	.1198	.1437	.1917	.2396	.2875	
	Z	.1728	.3456	.4320	.5183	.6911	.8639	1.0367	



$\theta \backslash R$		List 1-3						
		0.2	0.4	0.5	0.6	0.8	1.0	1.2
16°	X	.0493	.0986	.1232	.1479	.1972	.2464	.2957
	Z	.1719	.3438	.4297	.5157	.6876	.8595	1.0314
16° 30'	X	.0507	.1013	.1266	.1520	.2026	.2533	.3039
	Z	.1710	.3420	.4275	.5130	.6840	.8550	1.0260
17°	X	.0520	.1040	.1300	.1560	.2080	.2600	.3120
	Z	.1701	.3402	.4253	.5103	.6804	.8505	1.0207
17° 30'	X	.0534	.1067	.1334	.1601	.2134	.2668	.3201
	Z	.1692	.3384	.4230	.5077	.6769	.8461	1.0153
18°	X	.0547	.1094	.1367	.1641	.2188	.2735	.3281
	Z	.1683	.3366	.4208	.5050	.6733	.8416	1.0099
18° 30'	X	.0560	.1120	.1401	.1681	.2241	.2801	.3361
	Z	.1674	.3349	.4186	.5023	.6697	.8371	1.0046
19°	X	.0573	.1147	.1434	.1720	.2294	.2867	.3440
	Z	.1665	.3331	.4163	.4996	.6661	.8327	.9992
19° 30'	X	.0587	.1173	.1466	.1760	.2346	.2933	.3519
	Z	.1656	.3313	.4141	.4969	.6625	.8282	.9938
20°	X	.0600	.1199	.1499	.1799	.2398	.2998	.3598
	Z	.1647	.3295	.4118	.4942	.6589	.8237	.9884
20° 30'	X	.0613	.1225	.1531	.1838	.2450	.3063	.3675
	Z	.1638	.3277	.4096	.4915	.6553	.8192	.9830
21°	X	.0625	.1251	.1564	.1876	.2502	.3127	.3753
	Z	.1629	.3259	.4073	.4888	.6517	.8147	.9776
21° 30'	X	.0638	.1276	.1596	.1915	.2553	.3191	.3829
	Z	.1620	.3241	.4051	.4861	.6481	.8101	.9722
22°	X	.0651	.1302	.1627	.1953	.2604	.3255	.3906
	Z	.1611	.3222	.4028	.4834	.6445	.8056	.9667
22° 30'	X	.0664	.1327	.1659	.1991	.2655	.3318	.3982
	Z	.1602	.3204	.4005	.4807	.6409	.8011	.9613
23°	X	.0676	.1352	.1691	.2029	.2705	.3381	.4057
	Z	.1593	.3186	.3983	.4779	.6372	.7965	.9559
23° 30'	X	.0689	.1377	.1722	.2066	.2755	.3444	.4132
	Z	.1584	.3168	.3960	.4752	.6336	.7920	.9504

$\theta \backslash R$		List 1-4						
		0.2	0.4	0.5	0.6	0.8	1.0	1.2
24°	X	.0701	.1402	.1753	.2104	.2805	.3506	.4207
	Z	.1575	.3150	.3937	.4725	.6300	.7874	.9449
24° 30'	X	.0714	.1427	.1784	.2141	.2854	.3568	.4281
	Z	.1566	.3132	.3914	.4697	.6263	.7829	.9395
25°	X	.0726	.1452	.1815	.2178	.2903	.3629	.4355
	Z	.1557	.3113	.3892	.4670	.6226	.7783	.9230
25° 30'	X	.0738	.1476	.1845	.2214	.2952	.3690	.4429
	Z	.1547	.3095	.3869	.4642	.6190	.7737	.9285
26°	X	.0750	.1501	.1876	.2251	.3001	.3751	.4502
	Z	.1538	.3077	.3846	.4615	.6153	.7691	.9230
26° 30'	X	.0762	.1525	.1906	.2287	.3049	.3812	.4574
	Z	.1529	.3058	.3823	.4587	.6116	.7645	.9174
27°	X	.0774	.1549	.1936	.2323	.3098	.3872	.4646
	Z	.1520	.3040	.3800	.4560	.6079	.7599	.9119
27° 30'	X	.0786	.1573	.1966	.2359	.3145	.3932	.4718
	Z	.1511	.3021	.3777	.4532	.6042	.7553	.9064
28°	X	.0798	.1597	.1996	.2395	.3193	.3991	.4790
	Z	.1501	.3003	.3753	.4504	.6005	.7507	.9008
28° 30'	X	.0810	.1620	.2025	.2430	.3240	.4051	.4861
	Z	.1492	.2984	.3730	.4476	.5968	.7460	.8952
29°	X	.0822	.1644	.2055	.2466	.3288	.4110	.4931
	Z	.1483	.2966	.3707	.4448	.5931	.7414	.8897
29° 30'	X	.0834	.1667	.2084	.2501	.3335	.4168	.5002
	Z	.1473	.2947	.3684	.4420	.5894	.7367	.8841
30°	X	.0845	.1691	.2113	.2536	.3381	.4226	.5072
	Z	.1464	.2928	.3660	.4392	.5856	.7321	.8785
30° 30'	X	.0857	.1714	.2142	.2571	.3428	.4285	.5141
	Z	.1455	.2909	.3637	.4364	.5819	.7274	.8728
31°	X	.0868	.1737	.2171	.2605	.3474	.4342	.5211
	Z	.1445	.2891	.3613	.4336	.5781	.7227	.8672
31° 30'	X	.0880	.1760	.2200	.2640	.3520	.4400	.5280
	Z	.1436	.2872	.3590	.4308	.5744	.7180	.8616

$\theta \backslash R$		List 1-5						
		0.2	0.4	0.5	0.6	0.8	1.0	1.2
32°	X	.0891	.1783	.2228	.2674	.3566	.4457	.5348
	Z	.1427	.2853	.3566	.4280	.5706	.7133	.8559
32° 30'	X	.0903	.1806	.2257	.2708	.3611	.4514	.5417
	Z	.1417	.2834	.3543	.4251	.5668	.7085	.8502
33°	X	.0914	.1828	.2285	.2742	.3656	.4570	.5485
	Z	.1408	.2815	.3519	.4223	.5630	.7038	.8445
33° 30'	X	.0925	.1851	.2313	.2776	.3701	.4627	.5552
	Z	.1398	.2796	.3495	.4194	.5592	.6990	.8388
34°	X	.0937	.1873	.2341	.2810	.3746	.4683	.5619
	Z	.1389	.2777	.3471	.4166	.5554	.6943	.8331
34° 30'	X	.0948	.2895	.2369	.2843	.3791	.4739	.5686
	Z	.1379	.2758	.3447	.4137	.5516	.6895	.8274
35°	X	.0959	.1918	.2397	.2877	.3835	.4794	.5753
	Z	.1369	.2739	.3424	.4108	.5478	.6847	.8216
35° 30'	X	.0970	.1940	.2425	.2910	.3880	.4850	.5820
	Z	.1360	.2720	.3399	.4079	.5439	.6799	.8159
36°	X	.0981	.1962	.2452	.2943	.3924	.4905	.5886
	Z	.1350	.2700	.3375	.4050	.5401	.6751	.8101
36° 30'	X	.0992	.1984	.2480	.2976	.3968	.4960	.5952
	Z	.1340	.2681	.3351	.4021	.5362	.6702	.8043
37°	X	.1003	.2006	.2507	.3009	.4011	.5014	.6017
	Z	.1331	.2662	.3327	.3992	.5323	.6654	.7985
37° 30'	X	.1014	.2027	.2534	.3041	.4055	.5069	.6082
	Z	.1321	.2642	.3303	.3963	.5284	.6605	.7927
38°	X	.1025	.2049	.2561	.3074	.4098	.5123	.6147
	Z	.1311	.2623	.3278	.3934	.5245	.6557	.7868
38° 30'	X	.1035	.2071	.2588	.3106	.4141	.5177	.6212
	Z	.1302	.2603	.3254	.3905	.5206	.6508	.7809
39°	X	.1046	.2092	.2615	.3138	.4184	.5230	.6276
	Z	.1292	.2584	.3229	.3875	.5167	.6459	.7751
39° 30'	X	.1057	.2113	.2642	.3170	.4227	.5284	.6340
	Z	.1282	.2564	.3205	.3846	.5128	.6410	.7692

							List 1-6	
$\theta \backslash R$		0.2	0.4	0.5	0.6	0.8	1.0	1.2
40°	X	.1067	.2135	.2668	.3202	.4270	.5337	.6404
	Z	.1272	.2544	.3180	.3816	.5088	.6360	.7632
40° 30'	X	.1078	.2156	.2695	.3234	.4312	.5390	.6468
	Z	.1262	.2524	.3155	.3786	.5049	.6311	.6573
41°	X	.1089	.2177	.2721	.3266	.4354	.5443	.6531
	Z	.1252	.2504	.3131	.3757	.5009	.6261	.7513
41° 30'	X	.1099	.2198	.2748	.3297	.4396	.5495	.6594
	Z	.1242	.2485	.3106	.3927	.4969	.6211	.7454
42°	X	.1110	.2219	.2774	.3329	.4438	.5548	.6657
	Z	.1232	.2465	.3081	.3697	.4929	.6161	.7394
42° 30'	X	.1120	.2240	.2800	.3360	.4480	.5600	.6720
	Z	.1222	.2444	.3056	.3667	.4889	.6111	.7333
43°	X	.1130	.2261	.2826	.3391	.4522	.5652	.6782
	Z	.1212	.2424	.3030	.3637	.4849	.6061	.7273
43° 30'	X	.1141	.2281	.3852	.3422	.4563	.5704	.6844
	Z	.1202	.2404	.3005	.3606	.4808	.6010	.7212
44°	X	.1151	.2302	.2878	.3453	.4604	.5755	.6906
	Z	.1192	.2384	.2980	.3576	.4768	.5960	.7152
44° 30'	X	.1161	.2323	.2903	.3504	.4645	.5807	.6968
	Z	.1182	.2364	.2954	.3545	.4727	.5909	.7091
45°	X	.1172	.2343	.2929	.3515	.4686	.5858	.7029
	Z	.1172	.2343	.2929	.3515	.4686	.5858	.7029