

## 8040/55M CANNED CYCLE PARAMETERS

<b>Complex deep hole drilling</b>	format:\	<b>G69</b> G98/G99 X Y Z I B C D H J K L R
<b>Drilling canned Cycle</b>		<b>G81</b> G98/G99 X Y Z I K
<b>Drilling canned Cycle with dwell</b>		<b>G82</b> G98/G99 X Y Z I K
<b>Simple deep hole drilling</b>		<b>G83</b> G98/G99 X Y Z I J
<b>Tapping canned cycle</b>		<b>G84</b> G98/G99 X Y Z I K R
<b>Reaming canned cycle</b>		<b>G85</b> G98/G99 X Y Z I K
<b>Boring cycle with withdrawal in rapid</b>		<b>G86</b> G98/G99 X Y Z I K
<b>Rectangular pocket canned cycle</b>		<b>G87</b> G98/G99 X Y Z I J K B C D H L V
<b>Circular pocket canned cycle</b>		<b>G88</b> G98/G99 X Y Z I J B C D H L V
<b>Boring cycle with withdrawal at feedrate</b>		<b>G89</b> G98/G99 X Y Z I K

G8? or G69 G98/G99 X Y Z I K have the standard meaning for all the cycles.

**I= total depth \*\*\*exception G83, I = drilling step**

**K= dwell time \*\*\* exception G87 K= distance from center to edge of pocket**

Lets go over the other parameters for each cycle:

- B:** G69,G87,G88----drilling step in axis longitudinal to the main plane
- C:** G69----- distance from the previous drilling step  
G87, G88----- milling pass along the main plane
- D:** G69,G87, G88--- distance between the reference and surface of the part
- H:** G69 -----distance the axis will withdraw after each drilling step  
G87,G88----- the feedrate for the finishing pass
- J:** G69----- how many drilling steps the tool withdraws to reference plane  
G83 ----- number of steps which the drill is to make  
G87 ----- distance from center to the edge of the pocket  
G88----- radius of the pocket
- L:** G69----- minimum value which the drilling step can acquire  
G87, G88 ----- finishing pass along the main plane
- R:** G69 ----- factor which reduces the drilling step “B”  
G84 ----- defines the type of tapping: normal or rigid
- V:** G87,G88-----defines tool penetrating feedrate

### **Canned Cycle Area of influence:**

Once a canned cycle has been defined it remains active until cancelled. In other words every time a block has some axis movement programmed, the machining operation of the canned cycle is active also. If you program N at the end of the block, the CNC repeats the programmed move and the machining operation.

**G98:**withdrawal of tool as far as the initial plane

**G99:**withdrawal of tool as far as the reference plane

**G80:** cancels the canned cycle

**G79:** allows modifications of parameters within the canned cycle. programmed alone in a block

### **General Considerations:**

- a) a canned cycle can be defined at any point in a program.
- b) calls to subroutines can be made while the canned cycle is active
- c) execution of a canned cycle will not alter the history of previous G functions
- d) a canned cycle can be entered with M3 or M4. if no direction is entered, CNC assumes M3
- e) execution of a canned cycle cancels radius compensation. equivalent to G40
- f) tool length compensation must be programmed in the before the canned cycle or same block

# MULTIPLE MACHINING

<b>Multiple machining in a straight line pattern</b>	<b>G60</b> A (XI)or(XK)or(IK) P Q R S T U V
<b>Multiple machining in a rectangular pattern</b>	<b>G61</b> A B (XIor XK or IK ) (YJ orYD or JD) P Q R S T U V
<b>Multiple machining in a grid pattern</b>	<b>G62</b> A B (XIorXK or IK) ( YJorYD orJD) P Q R S T U V
<b>Multiple machining in a circular pattern</b>	<b>G63</b> X Y (I or K) C F P Q R S T U V
<b>Multiple machining in a arc pattern</b>	<b>G64</b> X Y B (I or K) C F P Q R S T U V
<b>Multiple machining by means of an arc chord</b>	<b>G65</b> X Y (A or I) C F

- A:**----- defines the angle which forms the machining pass with the abscissa axis
- B:**----- G61----- defines the angle formed by two machining paths.  
G64 ---- defines the angular stroke of the machining path
- C:**----- indicates how the movement is made between machining points 0=G0,1=G1,2=G2, 3=G3
- D:**----- number of operations in the ordinate axis
- F:**----- feedrate used between points
- I:**----- G60,G61,G62 -- pitch between machining operations  
G63,G64----- pitch angle between machining operations  
G65----- defines the chord length
- J:**-----pitch between machining operations according to the ordinate axis
- K:**----- number of total machining operations
- PQRSTUV:**-----points where it is not required to machine
- X:**----- G61,G62 ----- length of the machining path  
G63,G64,G65 -- distance from the starting point to center along the abscissa axis
- Y:**----- G61,G62----- pitch between machining operations according to the ordinate axis  
G63,G64,G65--- distance from the starting point to center along the ordinate axis

## General considerations:

Multiple functions are defined as a series of functions which allow a machining operation to be repeated along a given path.

The programmer will select the type of machining which can be a canned cycle or a modal subroutine.

These functions must be defined every time they are used. These functions will only make sense if they are under the influence of a canned cycle or modal subroutine

The following operations will be done under the same working conditions defined by the canned cycle

## To perform multiple machining, follow these steps:

- 1) move the tool to the first point of the multiple machining operation
- 2) define the canned cycle or modal subroutine to be repeated at all the points
- 3) defined the multiple operation to be performed