



## FANUC Spindle number over 24 Setting (For example Tool #25), T25


1. Go back to tool origin; Go to MDI Mode, type M20, Execute. (Tool will go back to origin.) Type M94, Execute. (Tool number reset).
2. Press SYSTEM→ Press Next (+) 3 times→PMCMNT (Picture 1) →DATA (Picture 2)→ Press any letter (A-Z) (Picture 3)→ZOOM.



Picture 1



Picture 2



Picture 3

3. See Picture 4 and 5. Make sure 0 position number is 99 (data number) and position of numbers 1-24 are the same as the data numbers 1-24.

PMC MAINTENANCE		RUN	***
PMC PARAM (DATA TABLE)		(PAGE	1/1429)
NO. 1	BCD:BYTE NO PROT.		
NO.	ADDRESS	DATA	
0	D0000	99	
1	D0001	1	
2	D0002	2	
3	D0003	3	
4	D0004	4	
5	D0005	5	
6	D0006	6	
( )			
A) ^			
MDI	STOP	***	***
		09:47:30	
(	LIST	G-SRCH	SEARCH

Picture 4

PMC MAINTENANCE		RUN	***
PMC PARAM (DATA TABLE)		(PAGE	4/1429)
NO. 1	BCD:BYTE NO PROT.		
NO.	ADDRESS	DATA	
21	D0021	21	
22	D0022	22	
23	D0023	23	
24	D0024	24	
25	D0025	0	
26	D0026	0	
27	D0027	0	
( )			
A) ^			
MDI	STOP	***	***
		09:48:35	
(	LIST	G-SRCH	SEARCH

Picture 5

4. See picture 6 , the position number 47 (Spindle tool number) is 0.

PMC MAINTENANCE RUN \*\*\*

PMC PARAM (DATA TABLE) (PAGE 7/1429)

NO. 1 BCD:BYTE NO PROT.

NO.	ADDRESS	DATA
42	D0042	0
43	D0043	0
44	D0044	0
45	D0045	7
46	D0046	1
47	D0047	0
48	D0048	7

SPD. NO (SPINDLE TOOL NO. )

A) ^

MDI STOP \*\*\* \*\* 09:49:08

LIST G-SRCH SEARCH

Picture 6

5. See picture 7, position number 47 change to from 0 to 25 (spindle become number T25.)

PMC MAINTENANCE RUN \*\*\*

PMC PARAM (DATA TABLE) (PAGE 7/1429)

NO. 1 BCD:BYTE NO PROT.

NO.	ADDRESS	DATA
42	D0042	0
43	D0043	0
44	D0044	0
45	D0045	7
46	D0046	1
47	D0047	25
48	D0048	7

SPD. NO (SPINDLE TOOL NO. )

A) ^

MDI STOP \*\*\* \*\* 09:49:33

LIST G-SRCH SEARCH

Picture 7