## PROCEDURE TO SET UP EMC 35100

 Set up leveling pad, screws (total 14 pieces), and leveling machine.






2. Remove the magazine supporter.

3. Remove the bracket(red) on the X-axis(facing machine'sright hand side).

4. Remove the set screw (red) from the Y-axis (in front).





5. Reposition the electricity cabinet and main power switch.






6. Reposition the control panel.





7. Turn on the machine.
Slowly move the Z up (by pressing "+").
Remove the



spindle head support. Move the Z down. The counterbalancing weight should be up. Remove the bar.



8. Assemble the splash guard and way cover.



9. Put in feed mode and set override to 10%. This step must be performed before home machine.