

**E-Lathe 1440V  
For Single Phase  
(1PH) wiring:  
Connect L1 & L3  
wires (only)**

**The coolant  
pump also  
needs be  
changed to  
single phase,  
to the  
MC-8150-1**



