E-mill Models For Single Phase 220V (1PH) wiring: Connect R & T & Ground

