



ACER - 618

Main control power & motors circuit diagram