



Springwood Industrial, Inc.
1062 N. Kraemer Place
Anaheim, CA 92806
Tel: 714-632-9701 Fax: 714-632-9730
<http://www.aceronline.net>

info@aceronline.net

Klim Industrial, Inc.
244 N. Randolphville Road
Piscataway, NJ 08854
Tel: 732-752-9100 Fax: 732-752-9101
<http://www.aceronline.net>

acer_klim@yahoo.com

PROCEDURE TO REWIRE MAGNETIC SEPARATOR AND PAPER FILTER FROM 220V TO 440V

1. Replace the Magnetic Separator motor from 220V to 440V.



2. Replace the Paper Filter motor from 220V to 440V.



3. Rewire the transformer from 220V to 440V.



4. Rewire the coolant pump motor from 220V to 440V.

